

## County Surveyor's Record, Douglas County, Oregon

Survey No. ....

Made for C. E. Amstary

T.29S. R4W.

Description of Survey  
 Chammen — ~~James~~ <sup>Ralph</sup> Johnson and Jesse Smith

Began survey at the North-west corner of Sec. 24 T.29S. R4W. This corner set and old B.T.s standing.

Instrument used was a Young & Co's Burt Patent Solar Compass, reading to single minutes on horizontal limb, Dec. Arc and Lat. arc reading to minutes.

A Gunter's 33 ft. (50 lbs) chains with eleven marking pins were used to measure.

Aug. 25 — Ran East on random line from North-west corner of sec 24. at

38.08 I fell 60 lbs. North of the Nor.  $\frac{1}{4}$  corner bet. secs. 13 & 24. True bearing of west half of line bet. these secs is S 89° 06' E. From the said  $\frac{1}{4}$  corner I continued East on random at 24.50 set temporary stake  $\frac{1}{2}$  blazed line could be found East of said  $\frac{1}{4}$  corner.

Aug. 26. Began at the  $\frac{1}{4}$  corner on East side of sec. 24 and run random line North at

15.34 I fell 21 lbs East of temporary stake set the previous evening. Continue on North on random line at

39.63 I fell 93 lbs. West of section corner on Township line for secs. 13 and 24. True bearing of North  $\frac{1}{2}$  of line on East side sec. 24 is North 1° 21' East. Corner of for secs 13 & 24 set and aid trees remarked.

From the  $\frac{1}{4}$  cor on East side of sec. 24 I ran south on random line at

39.52 I fell 30 lbs East of cor. for secs 24 & 25. Find corner set and old B.T.s remarked. The true bearing of ~~line~~ on South  $\frac{1}{2}$  of line on East side of sec 24 is S 00° 26' West.

From the sec corner for secs 24 & 25 I run random West and make diligent search for old line and old corners but none could be found at

62.50 I set temporary stake South of the North west corner of Sec. 24