

COUNTY SURVEYOR'S RECORD, DOUGLAS COUNTY, OREGON

Survey No. Made on Nov. 18-21-22 1918
 In Town. 30 3. Range 4 West Sec. Cl.# 48
 Made for W.E. St. John
 Purpose of survey was to set the lines around
 said claim No. 48

Survey No. Made on
 In Town. Range Sec.
 Made for
 Purpose of

F.B. 14 = 45
 M.S. 48

I began the survey at the N.E. Cor. of Claim No. 48 in above tp. and
 rg. I find an old stake at this corner and other evidence to show that I
 have the true location of said corner. I reset this corner with a 1" X 48"
 chs. G.I.P. an call it point "A". From point "A" I run a true line S,00°-20' W.
 46.80 to the S.E. Cor. of claim 48 which I find is marked with a stake set agaist
 a fence post. I take the position of this post and stake as the true corner
 and call it point "B".
 I then return to point "A" or the N.E. Cor. of cl. # 48 and run a line S.89°-
 03' W. a distance of
 3,53 and set in a 4" x 40" cedar stake for the S.W. Cor. of a certain lot. I call
 this stake point "C" and continue my line on on the same bearing and at the
 full distance of
 23.53 I find the 1/4 cor. bet. secs. 3 and 10. I reset the same as recorded else-
 where. I begin new chaining and bearing here, by running N.88°-14' W.
 and at a distance of
 19.30 I fall on the N.W. Cor. of Cl. # 48 as set in by some previous County Surveyor.
 I note old Cedar stake and bearing tree marked 1/2 "S". I reset corner as
 noted in records. I then return to point "A" and run a true line N.00°-11'E.
 12.10 to the N.W. Cor. of Cl. # 49 which is a stake set in by Sur. Frank Cain. I call
 this N.W. Cor. point "D". From point "D" I run a line westerly a distance of
 3.34 to an old stake with B.T.s.. I do not molest this stake and call it point
 "E" in my notes. I then return to point "C" or t e S.W. Cor. of the lot and
 run a true line N.01°-06'E. to point "E" but do not chain the dist. This
 last line completes the work done for Mr. StJohn.
 A new Gurley transit was used. Sun lines were run. The chaining was
 fairly good.

Chainmen { R.D. Morrison
 E.W. Ormiston

J. C. Frear
 Dep. Co. Surveyor.

MAP OF W.E. ST JOHN RANCH

IN
SECS 3 & 10 - T.30 S. - R.4 W. - W.M.

Douglas Co., Oregon.

Office of M. B. Germond Co Surv
Dec 1918

