

# SECTION 33, T.29S., R.4W.

## COUNTY SURVEYORS DO NOT REMOVE FROM

28 27  
33 34

3/4" I.P.  
16" Fir N. 11° 30' W. 27.5  
28" Fir S. 60° E. 16.5  
24" Cedar S. 47° W. 17.8  
(Found)

1285.0

1" I.P.  
16" Madrona N. 15° 25' E. 15.1  
14" Madrona S. 31° 30' W. 7.6

1285.0

1" I.P.  
12" Fir S. 0° 35' E. 10.3  
20" Fir N. 70° W. 9.7

1285.0  
N. 3° 19' E. 5140.0

1285.0

1" I.P.  
20" Madrona N. 86° 45' W. 39.3  
18" Madrona S. 23° 53' W. 37.3

1285.0

33 34  
299.6

Renew  
16" Madrona N. 42° 42' E. 46.5  
20" Fir N. 72° 42' W. 36.8  
Found 2" I.P.

(Found) 1/2" I.P.  
8" Madrona S. 3° E. 18.5  
6" Fir S. 26° 30' W. 23.1

MAP FILE MS 130

26" Fir N. 21° 30' W. 15.2  
10" Madrona N. 78° 30' E. 21.1  
1/4" I.P. (Found)  
East 458.04  
1/4" I.P.  
4 28" Fir S. 45° E. 7.3  
24" Fir S. 35° W. 19.8  
(Found)

THIS COPY MADE FROM  
A XEROX 2510  
DATE 2-17-89

FILED  
RECEIVED

JUN 5 1957

COUNTY SURVEYOR  
REGULAS