



NOTE
 Site is in the city of Reedsport and is in a fire zone, fireproof buildings being required. There are no setback lines and no contemplated street widenings. Sewage outflow is governed by tide and drainage conditions are poor. Soil is sandy.

SURVEY OF LOTS 1 & 2, EXCEPT THE NORTHERLY 10 FT. THEREOF, IN BLOCK 83 IN "AMENDED PLAT OF RAILROAD ADDITION" TO THE CITY OF REEDSPORT, DOUGLAS COUNTY, ORE.

STANDARD OIL COMPANY
 OF CALIFORNIA
SURVEY OF SERVICE STATION SITE
5TH ST. & FIR AVE.
REEDSPORT, OREGON
 Nov. 16, 1954 Scale 1"=10'
 Drawn By O.S.

THIS COPY MADE FROM
 A XEROX 2510
 DATE Aug. 4, 89

M 55-3