

SURVEY FOR BEN SERAFIN TO SET CENTER OF SECTION 4, T 27S, R 3W, W.M.

JUNE, 1976

BY HAROLD BALL CIVIL ENGINEER, ROSEBURG, ORE.



1" = 400'

BASE OF BEARING - SOUTH LINE
STANDLEY SUBDIVISION

32 33
5 4

2714.72'

NOTE
RESET AS PER NOTES BY R.E. STUNTZNER
SEE CS 58-53

N 88° 46' 53" W 2583.59'

8" MADRONE N 39° 30' W 49.1'
6" OAK N 55° 30' E 89.8'
8" OAK S 82° 45' E 61.1'

See BLM
Opinion
Dated
5/22/2001
CS 63/166
Concerning
this corner
DCSO -JC
5/29/2001

2681.22'

5 4
8 9

33 BRASS CAP BY BLM & B.T.'S AS PER RECORD

4

2737.31'

N 1° 12' 15" E

S 88° 46' 53" E 2582.46'

CENTER OF SECTION
4" CEDAR S 2° W 17.1'
12" CEDAR N 23° W 22.0'

4

3

BRASS CAP BY BLM & B.T.'S
AS PER RECORD

2706.02'

S 1° 12' 15" W

4 BRASS CAP C.S. 1957

9

8" CEDAR S 4° 30' E 22'
9" CEDAR N 41° 30' W 14'

- SET 5/8" I. ROD
- FOUND MONUMENT SHOWN

