



NARRATIVE:  
 MONUMENTS FOUND PER M41-40 AND M43-L. NE CORNER SET BY PROPORTIONING DISTANCE PER 321.07/556.73, AND USING RECORD BEARING TO ESTABLISH CORNER.  
 FIELD CREW: N. HIBBS & R. McALLISTER  
 OFFICE: DONALD BENTZ  
 DRAFTING: DEREK FEIGEL

LEGEND  
 ○ FD. 5/8" I.R.  
 ● SET 5/8" x 30" I.R. W/CAP STAMPED "I.E. ENGINEERING"

APPROVAL:  
*Keith L. Cubie* 10/25/93  
 DOUGLAS COUNTY PLANNING DEPARTMENT DATE

DRAINFIELD - REPAIR "A":  
 WQ - SS - DOUGLAS - UNRUH  
 TWP 26, R4, SEC 18  
 TAX ACCT. # 7028.03 TL 1300  
 SITE EVALUATION 9310 - 175

NOTE:  
 STRUCTURES ON PARCEL NO. 3 EXCEED THE MINIMUM SET-BACK TO THE ADJUSTED PROPERTY LINES.

DRAINFIELD - REPAIR "B":  
 WQ - SS - DOUGLAS - UNRUH  
 TWP 26, R4, SEC 18  
 TAX ACCT. # 7028.03 TL 1300  
 SITE EVALUATION 9310 - 174

COUNTY SURVEYORS FILE DATA  
 DO NOT REMOVE FROM FILE

REGISTERED  
 OREGON  
 LAND SURVEYOR

JULY 12, 1988  
 DONALD A. BENTZ  
 839

EXPIRES 12-31-93

PROPERTY LINE ADJUSTMENT  
 IN NE 1/4, SEC. 18, T26S, R4W,  
 WILLAMETTE MERIDIAN, DOUGLAS COUNTY, OREGON

SURVEYED FOR:  
 JOHN UNRUH  
 237 ACCORN DRIVE  
 ROSEBURG, OREGON 97470

SURVEYED BY:  
*i.e.*  
 ENGINEERING  
 1205 S.E. Court Street  
 Roseburg, Oregon 97470  
 PHONE (503) 673-0166  
 FAX (503) 440-9392

SCALE: AS NOTED DATE: AUG. 1993 211-07 PAGE: 1 OF 1