


FILED  
 Date: 10-5-1999 By: JP  
 This survey consists of:  
 Map: M133-31  
 Narrative:  
 Corner Ppt:

DOUGLAS COUNTY  
 SURVEYOR

**LEGEND**  
 ● Found 5/8" iron rod unless noted.  
 ○ Set 5/8" x 30" iron rod w/ plastic cap marked "LANDMARK PLS 2287"

**RECORD INFORMATION**  
 ( ) Record information per M64-35  
 [ ] Record information per PP 1994-0113



**NARRATIVE**  
 The purpose of this survey is to adjust the common boundary of the property described in Deed Reference Number 76-16376 and 94-13122 of the Deed Records of Douglas County, Oregon.

The monuments found were held as shown. The missing northeast corner of the property was established by intersecting record distances per M64-35. The north line was projected to intersect the easterly right of way of Interstate Highway 5.

**APPROVAL**  
 Keith L. Cubic  
 Douglas County Planning Director  
 10/5/99  
 Date  
 PLANNING FILE NO. 99-235

LINE TABLE		
LINE	LENGTH	BEARING
L1	3.43	N08°30'35"E

CURVE TABLE							
CURVE	RADIUS	LENGTH	CHORD BEARING	CHORD LENGTH	Record Radius	Record Length	Record Tangent
	297.19	96.86	S07°59'03"W	96.43	[299.26]	[97.16]	[49.01]
C1	357.19	116.41	S07°59'03"W	115.90	[359.26]	[116.64]	[58.84]

**SHEET 1 OF 1**  
**BOUNDARY LINE ADJUSTMENT**  
 DESCRIPTION OF SUBJECT PROPERTY  
 NE 1/4, Sec. 7, T.30S., R.5W., W.M.  
 Douglas County, Oregon  
 Sept. 1999

FOR: Douglas County Public Works  
 1036 SE Douglas, Rm 304  
 Roseburg, Oregon

REGISTERED PROFESSIONAL LAND SURVEYOR  
 Mark A. Hemburger

OREGON  
 JULY 16, 1987  
 MARK A. HEMBURGER  
 2287

EXPIRES JUNE 30, 2001

**Land Mark**  
 SURVEYING & DEVELOPMENT  
 727 SE Cass Ave., Suite 415  
 Roseburg, Oregon 97470  
 Tel (541) 677-9400  
 Fax (541) 677-9401