

100—FOUND MONUMENT

CORNER F-9, (GCDB 300560) N 1/16 CORNER OF SECTIONS 8 & 9 T. 28 S., R. 7 W., W.M.

FEBRUARY 1972 VIRGIL L. BROADWATER (MAP FILE M44-46) SET 1" IRON PIPE, 30" IN GROUND, 6" ABOVE GROUND FROM WHICH: A D.FIR 12" DIA., BEARS N 42°30' E, 17.0' MKD: 1/16 S9 BT A MADRONE 16" DIA., BEARS S 17°30' E, 15.6' MKD: 1/16 S9 BT A D.FIR 14" DIA., BEARS N 79°30' W, 29.1' MKD: 1/16 S8 BT

APRIL 1983 - JANUARY 1984 BLM RESURVEY BY BISHOP AND ROGERS UNDER GROUP NO. 1124 (DCSO RECORDS VOLUME 46, PAGE 17752)

THE N 1/16 SECTION CORNER OF SECTIONS 8 & 9, ESTABLISHED AND RECORDED BY VIRGIL L. BROADWATER, REGISTERED LAND SURVEYOR NO. 682, IN 1972, AND ACCEPTED AS THE CORNER, MONUMENTED WITH AN IRON PIPE, 1" DIA., FIRMLY SET, PROJECTING 4" ABOVE THE GROUND, FROM WHICH BEARING TREES MKD. BY BROADWATER: A FIR 14" DIA., BEARS N 42-1/2° E, 27 LKS. DIST. WITH SCRIBE MARKS 1/16 VISIBLE ON AN OPENED BLAZE A MADRONE 16" DIA., BEARS S 17-1/2° E, 24 LKS DIST. WITH SCRIBE MARKS 1/16 S9 BT VISIBLE ON A PARTIALLY HEALED BLAZE A FIR 16" DIA., BEARS N 79-1/2° W, 45 LKS. DIST. WITH HEALED BLAZE AND A BEARING TREE OF NO KNOWN RECORD. A FIR 14" DIA., BEARS S 04° E, 22 LKS. DIST. WITH HEALED BLAZE AT THE CORNER POINT, SET AN ALUMINUM POST, 28" LONG, 2-1/2" DIA., 22" IN THE GROUND, DIRECTLY ATOP THE 1" IRON PIPE, WITH ALUMINUM CAP MKD: N 1/16 S8 S9 1983

MARCH 3, 2023 GARRETT FINCH AND CREW WITH MINISTER AND GLAESER SURVEYING FOUND 3-1/4" ALUMINUM CAP, 0.5' ABOVE GROUND FROM WHICH: A STUMP 10" DIA. (4" HIGH), BEARS N 82° W, 40.0' (NO RECORD) A STUMP 12" DIA, BEARS S 88° W, 34.0' WITH HEALED BLAZE (NO RECORD) A STUMP 6" DIA. (3" HIGH), BEARS N 20° E, 14.1' (NO RECORD) A STUMP 12" DIA. (5" HIGH), BEARS N 76° W, 29.5' WITH HEALED BLAZE (1972) A STUMP 8" DIA., BEARS S 48° E, 8.2' TO ROOTHOLE, STUMP BROKEN OFF AND LYING ALONGSIDE WITH HEALED BLAZE (NO RECORD) A STUMP 12" DIA., BEARS N 40° E, 17.5' TO ROOTHOLE, STUMP BROKEN OFF AND LYING ALONGSIDE (1972) NOTE: ALL STUMPS FOUND HAD A METAL TOP (SET CHAINING NAIL AT SIDE CENTER, BT SIGNS ON FRONT AND REAR, AND PAINTED RED BAND FOR EXISTING BT'S)

ESTABLISHED THE FOLLOWING: A FIR 8" DIA., BEARS N 18° W, 16.5' MKD: N 1/16 S8 BT A FIR 6" DIA., BEARS N 46° E, 18.7' MKD: N 1/16 S9 BT (SET CHAINING NAIL AT SIDE CENTER, NAIL AND WASHER STAMPED "PLS 2830" AT BASE OF BLAZE, BT SIGNS ON FRONT AND BACK AND PAINTED RED BAND FOR NEW BT)

101—FOUND MONUMENT

CORNER E-9, (GCDB 300600) CORNER OF SECTIONS 4, 5, 8 & 9 T. 28 S., R. 7 W., W.M.

MAY 30, 1854 (ORIGINAL) NATHANIEL FORD UNDER CONTRACT NO. 44 (DCSO RECORD VOLUME 14, PAGE 5772) SET A POST, CORNER OF SECTIONS 4, 5, 8 & 9, FROM WHICH: A B.OAK 10" DIA., BEARS S 33° E, 64 LKS. DIST. A B.OAK 7" DIA., BEARS N 40° E, 65 LKS. DIST. A B.OAK 18" DIA., BEARS S 78° W, 26 LKS. DIST. A W.OAK 8" DIA., BEARS N 40° W, 762 LKS. DIST.

1924 GLO RESURVEY BY MENSCH (DCSO RECORDS VOLUME 14, PAGES 5891-92) INTERSECT THE POINT FOR SECTION CORNER LOCATED BY RECORD MEASUREMENT FROM THE ORIGINAL BEARING TREES, MARKS ON ALL THESE TREES ARE OVERGROWN, BLAZES ARE PLAIN, NE TREE OPENED. AT THE EXACT CORNER POINT, SET AN IRON POST, 3' LONG, 2" DIA., 28" IN THE GROUND, WITH BRASS CAP MKD: T28S R7W S4 S5 S8 S9 1924 FROM WHICH THE ORIGINAL BEARING TREES: A B.OAK 14" DIA., BEARS N 79° E, 65 LKS. DIST. A B.OAK 18" DIA., BEARS S 70° E, 64 LKS. DIST. (NOT S 33° E) A B.OAK 30" DIA., BEARS S 80° W, 26 LKS. DIST. (NOT S 78° W) A W.OAK 20" DIA., BEARS N 38° W, 162 LKS. DIST. (NOT N 40° W, 762 LKS.) NEW BT'S: AN ASH 8" DIA., BEARS N 77° E, 18 LKS. DIST. MKD: T28S R7W S4 BT A CEDAR 10" DIA., BEARS S 77° E, 19 LKS. DIST. MKD: T28S R7W S9 BT A FIR 16" DIA., BEARS S 55° W, 34 LKS. DIST. MKD: T28S R7W S8 BT A CEDAR 10" DIA., BEARS N 62° W, 23 LKS. DIST. MKD: T28S R7W S5 BT

FEBRUARY - MARCH 1961 DOUGLAS COUNTY SURVEYORS OFFICE JAMES W. BYRON, MILO GODFREY, & CLETE PUTNAM (C.S. FILE 49/50-36) FOUND BRASS CAP AT CORNER FROM WHICH: A STUMP OF 8" NOW 14" ASH, BEARS N 77° E, 11.9' SHOWS GOOD SCRIBING NOW 16" CEDAR, DOWN, BEARS N 62° W, 15.2' SHOWS GOOD SCAR NO OTHER ORIGINAL OR 1924 SURVEY BT'S FOUND NEW BT'S: A W.OAK 6" DIA., BEARS N 41° E, 27.3' MKD: S4 T28S R7W CS BT A CEDAR 18" DIA., BEARS S 61-1/2° W, 49.5' MKD: S8 T28S R7W CS BT A W.OAK 5" DIA., BEARS N 19° E, 23.5' MKD: S4 CS BT NO TREES NEAR TO NW A R.FIR 18" DIA., BEARS S 5-1/2° E, 56.0' MKD: T28S R7W CS BT

FEBRUARY 1972 VIRGIL BROADWATER (MAP FILE M44-46) FOUND BRASS CAP

NOVEMBER 1974 HERBERT L. NORTHCRAFT FOUND 2 WITNESS TREES FOR CORNER AND NO BRASS CAP AN OAK, 6" DIA., BEARS N 41° E, 27.3' A FIR, 16" DIA., BEARS S 5-1/2° W, 56.1' AN OAK, 6" DIA., BEARS N 19° E, 23.5' (DISREGARDED)

OCTOBER 4, 1976 DOUGLAS COUNTY SURVEYORS OFFICE L.E. MONREAN & P.L. EARLE (C.S. FILE 59/74-22) FOUND NO TRACE OF BRASS CAP SET IN 1924 DID NOT FIND ANY ORIGINAL OR 1924 RESURVEY BT'S THREE BT'S FROM 1961 RENEWAL STILL STANDING, FROM WHICH I SET A BRASS CAP AFTER OPENING A W.OAK AND FINDING SCRIBING "T28S R7W S4 CS" ON THE UPPER BLAZE SET A BRAS CAP AT SECTION CORNER STAMPED: DOUGLAS COUNTY SURVEYORS OFFICE T28S R7W S4 S5 S8 S9 1976 FROM WHICH: A W.OAK 6" NOW 8" BEARS N 41° E, 27.3' WITH DOUBLE BLAZE AND MKD: T28S R7W S4 CS ON UPPER BLAZE AND LOWER BLAZE IS WELL HEALED A W.OAK 5" NOW 7" BEARS N 19° E, 23.5' WITH WELL HEALED DOUBLE BLAZE A R.FIR 18" NOW 24" BEARS S 2-1/2° E, 56.0' (REC S 5-1/2° E) WITH WELL HEALED DOUBLE BLAZE A CEDAR 18", NOW A WINDFALL, BEARS S 61-1/2° W, 49.5' LAYING BLAZE DOWN NEW BT: A 7" I.CEDAR BEARS N 65-1/2° W, 26.1' WITH DOUBLE BLAZE MKD: T28S R7W S5 CS BT

101 CONT.

APRIL 1983 - JANUARY 1984 BLM RESURVEY BY BISHOP AND ROGERS UNDER GROUP NO. 1124 (DCSO RECORDS VOLUME 46, PAGES 17752-53) THE CORNER OF SECTIONS 4, 5, 8 & 9, PERPETUATED & RECORDED BY JAMES W. BYRON, DEPUTY DOUGLAS COUNTY SURVEYOR, IN 1961, FROM A BT MARKED BY MENSCH, NO LONGER IN EXISTENCE, AND FURTHER PERPETUATED AND RECORDED BY LARRY MONREAN, DEPUTY DOUGLAS COUNTY SURVEYOR, IN 1976, MONUMENTED WITH AN IRON PIPE, 1-1/4" DIA., PROJECTING 10" ABOVE GROUND, WITH PROPERLY MARKED BRASS CAP. FROM WHICH THE REMAINS OF BEARING TREES MKD. BY BYRON: A W.OAK 6" DIA., BEARS N 19° E, 36 LKS. WITH HEALED DOUBLE BLAZE A W.OAK 8" DIA., BEARS N 41° E, 41 LKS. WITH MARKS T28S R7W S4 CS VISIBLE ON OPENED BLAZE A FIR 18" DIA., BEARS S 5-1/2° E, 86 LKS. WITH HEALED DOUBLE BLAZE AND BEARING TREES MKD. BY MONREAN: A CEDAR 8" DIA., BEARS N 65-1/2° W, 40 LKS. DIST. WITH SCRIBE MARKS T28S R7W S5 CS BT VISIBLE ON PARTIALLY HEALED BLAZE AND A NEW BEARING TREE: A FIR 8" DIA., BEARS S 60-1/2° W, 62 LKS. DIST. MKD: T28S R7W S8 BT

MAY 1991 - MAY 1994 BLM DEPENDENT RESURVEY BY BRYAN S. SEIBOLD, ROBERT J. CHAPPEL, CADASTRAL SURVEYORS UNDER GROUP NO. 1585 (DCSO RECORDS VOLUME 52, PAGES 2001-4) THE CORNER OF SECTIONS 4, 5, 8 & 9, MONUMENTED WITH AN IRON POST, 1-1/2" DIA., FIRMLY SET, PROJECTING 3" ABOVE GROUND, WITH BRASS CAP MKD: DOUGLAS COUNTY SURVEYORS OFFICE T28S R7W S4 S5 S8 S9 1976 FROM WHICH THE REMAINS OF THE BEARING TREES MKD. BY JAMES W. BYRON, DEPUTY COUNTY SURVEYOR, IN 1961: AN OAK 7" DIA., BEARS N 16-1/2° E, 36 LKS. DIST. WITH HEALED DOUBLE BLAZE (REC. N 19° E) AN OAK 9" DIA., BEARS N 39-1/2° E, 41 LKS DIST. WITH FRAGMENTARY SCRIBE MARKS VISIBLE ON PARTIALLY HEALED UPPER BLAZE OF DOUBLE BLAZE (REC. N 41° E) A FIR 20" DIA., BEARS S 5-1/2° E, 86 LKS. DIST. WITH HEALED DOUBLE BLAZE AND A BEARING TREE MKD. BY LARRY E. MONREAN, DEPUTY COUNTY SURVEYOR, IN 1976: A CEDAR 10" DIA., BEARS N 65-1/2° W, 40 LKS. DIST. WITH FRAGMENTARY SCRIBE MARKS VISIBLE ON PARTIALLY HEALED DOUBLE BLAZE AND A BEARING TREE MKD. BY ROGERS AND BISHOP: A FIR 12" DIA., BEARS S 60-1/2° W, 62 LKS. DIST. WITH HEALED DOUBLE BLAZE THE CORNER IS LOCATED NORTH, 0.40 CHAINS DIST. OF A DIRT ROAD, 20 LKS. WIDE, BEARS NE & SW

MARCH 20, 2023 GARRETT FINCH AND CREW WITH MINISTER AND GLAESER SURVEYING FOUND 2-1/2" BRASS CAP, 0.2' ABOVE GROUND FROM WHICH: AN OAK 8" DIA., BEARS N 18° E, 23.4' WITH BT SIGN (1961) AN OAK 12" DIA., BEARS N 40° E, 27.3' WITH HEALED BLAZE (1961) A CEDAR 12" DIA., BEARS N 62° W, 26.0' WITH HEALED BLAZE (1976) A FIR 16" DIA., BEARS S 59° W, 40.5' WITH HEALED BLAZE (1984) A FIR 22" DIA., BEARS S 07° E, 55.9' WITH HEALED BLAZE (1976) (SET CHAINING NAIL AT SIDE CENTER, BT SIGNS ON FRONT AND REAR, AND PAINTED RED BAND FOR EXISTING BT'S)

102—FOUND MONUMENT

CORNER F-10, (GCDB 320560) NW 1/16 CORNER OF SECTION 9 T. 28 S., R. 7 W., W.M.

APRIL 1983 - JANUARY 1984 BLM RESURVEY BY BISHOP AND ROGERS UNDER GROUP NO. 1124 (DCSO RECORDS VOLUME 46, PAGE 17760) THE W 1/16 SECTION CORNER OF SECTION 9, SET AN IRON POST, 28" LONG, 2-1/2" DIA., 24" IN THE GROUND, WITH BRASS CAP MKD: NW 1/16 S9 1983 FROM WHICH: A FIR 10" DIA., BEARS N 71-1/4° E, 9 LKS. DIST. MKD: NW 1/16 S9 BT A FIR 8" DIA., BEARS S 23-1/2° E, 52 LKS. DIST. MKD: NW 1/16 S9 BT

MARCH 22, 1984 BRUCE A. SHANER (MAP FILE M96-19) FOUND BLM BRASS CAP FOR THE NW 1/16 CORNER SECTION 9 JULY 26, 2000 GREGORY D. LANG (MAP FILE M135-25) FOUND BRASS CAP AT THE NW 1/16 CORNER FROM WHICH: A 15-1/2" FIR BEARS N 71-1/4° E, 5.94' A 14-1/2" FIR BEARS S 23-1/2° E, 34.32'

FEBRUARY 2, 2023 F. NEIL HIBBS (MAP FILE M178-61) FOUND BRASS CAP AND BT'S OF RECORD FOR THE NW 1/16 CORNER SECTION 9

MARCH 6, 2023 GARRETT FINCH AND CREW WITH MINISTER AND GLAESER SURVEYING FOUND 3" BRASS CAP, 0.4' ABOVE GROUND IN EAST/WEST BARB WIRE FENCE LINE FROM WHICH: A 7" DIA. WOOD POST BEARS 1.7' WEST A FIR 16" DIA. (DEAD), BEARS N 70° E, 5.9' WITH HEALED BLAZE (BLM 1984) A FIR 14" DIA. (DEAD), BEARS S 24° E, 34.4' WITH HEALED BLAZE (BLM 1984) (SET CHAINING NAIL AT SIDE CENTER, NAIL AND WASHER STAMPED "PLS 2830" (SET CHAINING NAIL AT SIDE CENTER, BT SIGNS ON FRONT AND REAR, AND PAINTED RED BAND FOR EXISTING BT'S)

ESTABLISHED THE FOLLOWING: A FIR 10" DIA., BEARS N 00° E, 86.1' MKD: NW 1/16 S9 BT A FIR 8" DIA., BEARS N 68° W, 62.7' MKD: NW 1/16 S9 BT (SET CHAINING NAIL AT SIDE CENTER, NAIL AND WASHER STAMPED "PLS 2830" AT BASE OF BLAZE, BT SIGNS ON FRONT AND BACK AND PAINTED RED BAND FOR NEW BT'S)

104—FOUND MONUMENT

CORNER G-9, (GCDB 300540) 1/4 CORNER OF SECTIONS 8 & 9 T. 28 S., R. 7 W., W.M.

MAY 30, 1854 (ORIGINAL) NATHANIEL FORD UNDER CONTRACT NO. 44 (DCSO RECORD VOLUME 14, PAGE 5772) SET 1/4 SECTION POST, FROM WHICH: A B.OAK 30" DIA., BEARS S 20° E, 150 LKS. A B.OAK 7" DIA., BEARS S 25° W, 165 LKS.

FEBRUARY 1953 CLAUDE KERR (C.S. FILE 41/120) A 3 X 4 CEDAR STAKE WAS SET BY PROPORTIONAL MEASURE (2567.1') A 12" CEDAR BEARS N 70° E, 11.6' MKD: 1/4 S BT A 12" LAUREL BEARS S 76° W, 26.6'

FEBRUARY - MARCH 1961 DOUGLAS COUNTY SURVEYOR OFFICE JAMES BYRON, MILO GODFREY & CLETE PUTNAM (C.S. FILE 49/50-37) FOUND BOTH BT'S AS RECORDED BY KERR, 1953 SET BRASS CAP AT CORNER MKD: COUNTY SURVEYORS OFFICE T28S 1/4 S8 S9 R7W 1961

104 CONT.

FEBRUARY 18, 1972 VIRGIL L. BROADWATER (C.S. FILE 55/239 AND M44-46) FOUND BRASS CAP, SET 1961 COUNTY SURVEYOR 18" CEDAR BEARS N 70° E, 11.6' SHOWS GOOD SCAR 15" MADRONE BEARS S 76° W, 27.0'

FEBRUARY 27, 1978 VIRGIL L. BROADWATER (MAP FILE M68-69) FOUND BRASS CAP

DECEMBER 2, 1978 VIRGIL L. BROADWATER (MAP FILE M74-50) FOUND BRASS DISK

APRIL 1983 - JANUARY 1984 BLM RESURVEY BY BISHOP & ROGERS UNDER GROUP NO. 1124 (DCSO RECORDS VOLUME 46, PAGES 17751)

THE 1/4 SECTION CORNER OF SECTIONS 8 & 9, REESTABLISHED BY PROPORTIONAL MEASUREMENT BY CLAUDE KERR, REGISTERED LOGGING ENGINEER, NO. 2125, IN 1953, PERPETUATED BY JAMES W. BYRON, DEPUTY DOUGLAS COUNTY SURVEYOR, IN 1961, AND ACCEPTED AS THE CORNER, MONUMENTED WITH AN IRON PIPE, 1-1/4" DIA., PROJECTING 8" ABOVE GROUND, WITH BRASS CAP MKD: COUNTY SURVEYORS OFFICE T28S 1/4 S8 S9 R7W 1961 FROM WHICH BEARING TREES BY KERR: A CEDAR 18" DIA., BEARS N 74-3/4° E, 19 LKS. DIST. WITH HEALED DOUBLE BLAZE A MADRONE 18" DIA., BEARS S 76-1/2° W, 42 LKS. DIST. WITH HEALED DOUBLE BLAZE

DECEMBER 1996 VIRGIL BROADWATER (MAP FILE M126-18) FOUND BRASS CAP MKD: COUNTY SURVEYORS OFFICE T28S 1/4 S8 S9 R7W 1961

MARCH 6, 2023 GARRETT FINCH AND CREW WITH MINISTER AND GLAESER SURVEYING FOUND 2-1/2" BRASS CAP, 0.7' ABOVE GROUND FROM WHICH: A CEDAR STUMP 30" DIA. (2" HIGH), BEARS N 80° E, 12.2' (1984) A MADRONE STUMP 28" DIA. (2"HIGH), BEARS S 72° W, 27.6' (1984) A 5/8" IRON ROD WITH YPC "HIBBS LS 52989" BEARS S 88° W, 204.2' A 5/8" IRON ROD WITH YPC "HIBBS LS 52989" BEARS N 66° E, 218.9' NOTE: HIBBS SET CORNERS DURING A SURVEY THAT HAS NOT YET BEEN RECORDED (SET CHAINING NAIL AT SIDE CENTER, BT SIGNS ON FRONT AND REAR, PAINTED RED BAND FOR EXISTING BT'S, AND SET POSTS WITH BT SIGNS AT 5/8" IRON RODS)

ESTABLISHED THE FOLLOWING: A FIR 16" DIA., BEARS N 82° W, 92.3' MKD: 1/4 S8 BT A FIR 10" DIA., BEARS N 18° W, 101.8' MKD: 1/4 S8 BT (SET CHAINING NAIL AT SIDE CENTER, NAIL AND WASHER STAMPED "PLS 2830" AT BASE OF BLAZE, BT SIGNS ON FRONT AND BACK AND PAINTED RED BAND FOR NEW BT'S)

108—FOUND MONUMENT

CORNER E-10, (GCDB 320600) W 1/16 CORNER OF SECTIONS 4 & 9 T. 28 S., R. 7 W., W.M.

OCTOBER 1974 HERBERT L. NORTHCRAFT (MAP FILE M54-54) SET A 5/8"x30" IRON ROD FROM WHICH: A FIR 12" DIA., BEARS S 53° W, 4' A CEDAR 13" DIA., BEARS S 53-1/2° W, 13' A CEDAR 10" DIA., BEARS N 44° W, 29'

NOVEMBER 1974 HERBERT L. NORTHCRAFT (MAP FILE M54-55) SET A 5/8"x30" IRON ROD FROM WHICH: A FIR 12" DIA., BEARS S 53-1/2° W, 4' A CEDAR 10" DIA., BEARS S 53-1/2° W, 13' A CEDAR 10" DIA., BEARS N 44° W, 29'

APRIL 1983 - JANUARY 1984 BLM RESURVEY BY BISHOP AND ROGERS UNDER GROUP NO. 1124 (DCSO RECORDS VOLUME 46, PAGE 17750) THE W 1/16 SECTION CORNER OF SECTIONS 4 & 9, ESTABLISHED AND RECORDED BY HERBERT L. NORTHCRAFT, REGISTERED LAND SURVEYOR, NO. 750, IN 1974, AND ACCEPTED AS THE CORNER, MONUMENTED WITH AN IRON ROD, 5/8" DIA., PROJECTING 6" ABOVE GROUND, FROM WHICH THE BEARING TREES MKD. BY NORTHCRAFT: A FIR 14" DIA., BEARS S 53° W, 6 LKS. DIST. WITH HEALED BLAZE A CEDAR 8" DIA., BEARS S 53° W, 44 LKS DIST. WITH HEALED BLAZE AT THE CORNER POINT, SET AN IRON POST, 28" LONG, 2-1/2" DIA., 22" IN THE GROUND, DIRECTLY ATOP THE IRON ROD, WITH BRASS CAP MKD: W 1/16 S4 S9 1983

MARCH 7, 2023 GARRETT FINCH AND CREW WITH MINISTER AND GLAESER SURVEYING FOUND 3" BRASS CAP, 0.4' ABOVE GROUND FROM WHICH: A 2" IRON PIPE LEANING NORTHEAST WITH 5/8" IRON ROD INSIDE, IN THE CENTER OF 7" WIDE CREEK BEARS N 77°58'43" W 15.86' (SURVEY COORDINATES) A FIR 22" DIA., BEARS S 52° W, 4.0' WITH HEALED BLAZE (1974) A CEDAR 10" DIA., BEARS N 42° W, 28.4' PARTIALLY HEALED BLAZE (1974) A CEDAR 8" DIA. (DEAD), BEARS S 50° W, 13.4' PARTIALLY HEALED BLAZE (1974) A CEDAR 10" DIA., BEARS S 08° W, 19.6' WITH HEALED DOUBLE BLAZE (NO RECORD) (SET CHAINING NAIL AT SIDE CENTER, BT SIGNS ON FRONT AND REAR, AND PAINTED RED BAND FOR EXISTING BT'S)

APRIL 1983 - JANUARY 1984 BLM RESURVEY BY BISHOP AND ROGERS UNDER GROUP NO. 1124 (DCSO RECORDS VOLUME 46, PAGE 17750) THE CORNER OF SECTIONS 8, 9, 16 & 17, FROM WHICH: A MADRONE 36" DIA., BEARS N 57-1/4° E, 100 LKS. DIST. WITH HEALED BLAZE AND THE REMAINS OF BEARING TREES MARKED BY MENSCH: A FIR, 8" DIA., BEARS N 51° E, 32 LKS. DIST. WITH HEALED SINGLE BLAZE A SAWED FIR STUMP 26" DIA., BEARS S 42° E, 24 LKS. DIST. WITH S16 VISIBLE ON CUT OPEN BLAZE A FIR 28" DIA., BEARS S 84° W, 42 LKS. DIST. WITH A HEALED BLAZE A FIR 24" DIA., BEARS N 39-1/4° W, 31 LKS. WITH HEALED FACE ANES RECORD: A FIR 20" DIA., BEARS N 74° E, 37-1/2 LKS. DIST. WITH HEALED BLAZE AT THE CORNER POINT, SET AN ALUMINUM POST, 28" LONG, 2-1/2" DIA., 24" IN THE GROUND, WITH ALUMINUM CAP MKD: T28S R7W S8 S9 S16 S17 1983 FROM WHICH A NEW BEARING TREE: A FIR 6" DIA., BEARS S 40-1/2° E, 241 LKS. DIST. MKD: T28S R7W S16 BT

JULY 1984 GLENN BAUGHMAN (RM 3-62)(C.S. FILE 58/144-12) FOUND 2-1/2" ALUMINUM PIPE WITH BLM ALUMINUM CAP FROM WHICH: A D.FIR 11" DIA., BEARS N 51° E, 21.4' WITH SCRIBE VISIBLE A D.FIR STUMP 29" DIA., BEARS S 42° E, 15.8' WITH SCRIBE VISIBLE A D.FIR 28" DIA., BEARS S 84° W, 27.7' WITH HEALED BLAZE A D.FIR 24" DIA., BEARS N 37° W, 20.4' WITH HEALED BLAZE A D.FIR 21" DIA., BEARS N 74° E, 24.2' WITH SCRIBE VISIBLE A D.FIR 6" DIA., BEARS S 40-1/2° E, 159.1' WITH SCRIBE VISIBLE

SEPTEMBER 1986 VIRGIL BROADWATER (MAP FILE M126-18) FOUND ALUMINUM CAP STAMPED: T28S R7W S8 S9 S16 S17 1983

MARCH 2, 2023 GARRETT FINCH AND CREW WITH MINISTER AND GLAESER SURVEYING FOUND 3-1/4" ALUMINUM CAP, 0.3' ABOVE GROUND FROM WHICH: A BARB WIRE FENCE CORNER RUNNING SOUTH & WEST BEARS NORTHEAST 2.2' A MADRONE 36" DIA., BEARS N 30° W, 56.6' PARTIAL HEALED BLAZE (1854) NOTE: BISHOP AND ROGERS IN 1984 FOUND A 36" MADRONE TO NORTHEAST, HOWEVER NO MADRONE TREES WERE FOUND TO NORTHEAST DURING THIS SURVEY. WE BELIEVE THE 36" MADRONE TREE FOUND THIS SURVEY TO BE ORIGINAL. A STUMP 10" DIA. (3.5" HIGH), BEARS N 52° W, 22.0' WITH BT SIGN (1966) A STUMP 10" DIA. (3.5" HIGH), BEARS N 52° W, 22.0' WITH PARTIALLY HEALED BLAZE AND ROTTED SCRIBED MARKS VISIBLE (1924) A STUMP 18" DIA. (3.5" HIGH), BEARS N 73° E, 25.1' WITH BT SIGN (1966) NOTE: C.S. FILE 52/79-1, NO RECORD DISTANCE TO N 73° E BEARING TREE. EXISTING SIGN ON 18" STUMP MKD: S 73° W 25.1' 12-2-66 WE SET A CHAINING NAIL AT 25.1' TO MATCH ORIGINAL BT SIGN A ROTTED STUMP 32" DIA. (2" HIGH), BEARS S 42° E, 15.8' (1924) A STUMP 34" DIA., BEARS S 82° W, 27.4' WITH BT SIGN (1924) (SET CHAINING NAIL AT SIDE CENTER, NAIL AND WASHER STAMPED "PLS 2830" AT BASE OF BLAZE, BT SIGNS ON FRONT AND REAR, AND PAINTED RED BAND FOR EXISTING BT'S)

ESTABLISHED THE FOLLOWING: A FIR 7" DIA., BEARS N 32° E, 17.4' MKD: T28S R7W S9 BT A FIR 8" DIA., BEARS S 80° E, 6.0' MKD: T28S R7W S16 BT (SET CHAINING NAIL AT SIDE CENTER, NAIL AND WASHER STAMPED "PLS 2830" AT BASE OF BLAZE, BT SIGNS ON FRONT AND BACK AND PAINTED RED BAND FOR NEW BT'S)

ESTABLISHED THE FOLLOWING: A FIR 7" DIA., BEARS N 32° E, 17.4' MKD: T28S R7W S9 BT A FIR 8" DIA., BEARS S 80° E, 6.0' MKD: T28S R7W S16 BT (SET CHAINING NAIL AT SIDE CENTER, NAIL AND WASHER STAMPED "PLS 2830" AT BASE OF BLAZE, BT SIGNS ON FRONT AND BACK AND PAINTED RED BAND FOR NEW BT'S)

ESTABLISHED THE FOLLOWING: A FIR 7" DIA., BEARS N 32° E, 17.4' MKD: T28S R7W S9 BT A FIR 8" DIA., BEARS S 80° E, 6.0' MKD: T28S R7W S16 BT (SET CHAINING NAIL AT SIDE CENTER, NAIL AND WASHER STAMPED "PLS 2830" AT BASE OF BLAZE, BT SIGNS ON FRONT AND BACK AND PAINTED RED BAND FOR NEW BT'S)

REGISTERED PROFESSIONAL LAND SURVEYOR

DANIEL A. RENTON 2830

Expires 12-31-2024

RECORD OF SURVEY

LOCATED IN A PORTION OF THE SE 1/4 OF THE SE 1/4 OF SECTION 8 THE NW 1/4, NE 1/4, SW 1/4 OF SECTION 9 T. 28 S., R. 7 W., W.M. PETTY LARSONY-TASK E DOUGLAS COUNTY, OREGON CONTRACT NO. 1204T020D0010 TASK ORDER NO. 140L4322F0063

FILED DATE: 3-5-2024 BY: THIS SURVEY CONSISTS OF: MAP: M185-3-A-D NARRATIVE: CORNER RPT: DOUGLAS COUNTY SURVEYOR

110—FOUND MONUMENT

CORNER J-8, (GCDB 260500) E 1/16 CORNER OF SECTIONS 8 & 17 T. 28 S., R. 7 W., W.M.

APRIL 1983 - JANUARY 1984 BLM RESURVEY BY BISHOP AND ROGERS UNDER GROUP NO. 1124 (DCSO RECORDS VOLUME 46, PAGE 17758) POINT FOR THE E 1/16 SECTION CORNER OF SECTIONS 8 & 17 SET AN IRON POST, 28" LONG, 2-1/2" DIA., 26" IN THE GROUND, WITH BRASS CAP MKD: E 1/16 S8 S17 1983 (NOTE: CAP MKD W 1/16) FROM WHICH: A FIR 10" DIA., BEARS N 87-1/2° E, 19 LKS. DIST. MKD: W 1/16 S8 BT A CEDAR 5" DIA., BEARS S 50° W, 45 LKS. DIST. MKD: W 1/16 S17 BT

MAY 1991 - MAY 1994 BLM DEPENDENT RESURVEY BY BRYAN S. SEIBOLD, ROBERT J. CHAPPEL, CADASTRAL SURVEYORS UNDER GROUP NO. 1585 AMENDED FIELD NOTES OF THE DEPENDENT RESURVEY OF THE EAST ONE-HALF OF THE LINE BETWEEN SECTIONS 8 & 17, T. 28 S., R. 7 W., W.M. THE PURPOSE OF THESE AMENDED FIELD NOTES IS TO CORRECT THE ERRONEOUSLY MARKED MONUMENT AND BEARING TREES AT THE E 1/16 SECTION CORNER OF SECTIONS 8 & 17, AS SHOWN IN THE OFFICIAL RECORD OF THE 1983-1984 BUREAU OF LAND MANAGEMENT SURVEY, APPROVED FEBRUARY 15, 1985. THE ERROR WAS DISCOVERED BY BRYAN S. SEIBOLD, CADASTRAL SURVEYOR, A FIELD INVESTIGATION OF THIS CORNER VERIFIED THAT THE ERROR EXISTED IN THE FIELD. THE MONUMENT AND BEARING TREES WERE CHANGED AND THOSE CHANGES ARE REFLECTED IN THE FOLLOWING AMENDED FIELD NOTES. THESE AMENDED FIELD NOTES ARE AUTHORIZED BY MEMORANDUM FROM THE CHIEF, BRANCH CADASTRAL SURVEY AND MAPPING SCIENCES, DATED FEBRUARY 28, 1994, FILE 9630 (942), A COPY OF WHICH FOLLOWS THESE RETURNS. POINT FOR THE E 1/16 SECTION CORNER OF SECTIONS 8 & 17 SET AN IRON POST, 28" LONG, 2-1/2" DIA., 26" IN THE GROUND, WITH BRASS CAP MKD: E 1/16 S8 S17 1983 FROM WHICH: A FIR 10" DIA., BEARS N 87-1/2° E, 19 LKS. DIST. MKD: E 1/16 S8 BT A CEDAR 5" DIA., BEARS S 50° W, 45 LKS. DIST. MKD: E 1/16 S17 BT

MARCH 20, 2023 GARRETT FINCH AND CREW WITH MINISTER AND GLAESER SURVEYING FOUND 3-1/4" BRASS CAP, FLUSH IN GROUND AND 1' EAST FROM CENTERLINE OF CREEK FROM WHICH: A ROOTHOLE BEARS N 83° E, 14.1' WITH 12" FIR TRUNK ALONGSIDE AND BT SIGN (1983) A CEDAR STUMP 16" DIA., BEARS S 51° W, 29.8' (1983) (SET CHAINING NAIL AT SIDE CENTER, BT SIGNS ON FRONT AND REAR, AND PAINTED RED BAND FOR EXISTING BT'S)

ESTABLISHED THE FOLLOWING: A FIR 12" DIA., BEARS S 43° E, 52.1' MKD: E 1/16 S17 BT A FIR 12" DIA., BEARS N 70° W, 7.4' MKD: E 1/16 S8 BT (SET CHAINING NAIL AT SIDE CENTER, NAIL AND WASHER STAMPED "PLS 2830" AT BASE OF BLAZE, BT SIGNS ON FRONT AND BACK AND PAINTED RED BAND FOR NEW BT'S)

111—FOUND MONUMENT

CORNER H-9, (GCDB 300520) S 1/16 CORNER OF SECTIONS 8 & 9 T. 28 S., R. 7 W., W.M.

FEBRUARY 1972 VIRGIL L. BROADWATER (MAP FILE M44-46) SET 1" IRON PIPE, 36" IN GROUND, 6" ABOVE GROUND FROM WHICH: A W.CEDAR 30" DIA., BEARS S 45°30' W, 50.6' MKD: 1/16 S8 BT A W.FIR 15" DIA., BEARS S 37°30' E, 38.0' MKD: 1/16 S9 BT

DECEMBER 2