

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 1 Page(s) 319)

 Set post 6" dia., 4 ft. long, 24" in ground, for cor. to Town. 19 & 20 S., R. 8 & 9 W., marked T19S S31 on NE.; R8W S6 on SE.; T20S S1 on SW.; R9W S36 on NW. faces, with 6 notches on each edge; from which
 Fir 30" dia., bears N.48°E., 23 lks. dist. mkd. T19S R8W S31 BT.
 Fir 20" dia., bears S.7°E., 43 lks. dist., mkd. T20S R8W S6 BT.
 Hemlock 8" dia., bears S.81°W., 37 lks. dist., mkd. T20S R9W S1 BT.
 Fir 30" dia., bears N.53°W., 78 lks. dist. mkd. T19S R9W S36 BT.

Fd. OK and used in GLO survey by Charles M. Collier, under Contract #580, dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 506)

GLO Resurvey by Thomas Tillman; Raymond Bicknell; Hans Thielsen; & Joseph Gawron, Cadastral Surveyors, under Group #305, Surveyed Aug. 1953/Sept. 1954 - (DCSO records Vol. 29 Page(s) 12353-54)

 The cor. of Tps. 19 & 20 S., R 8 W., determined at record bearings and distances from the original bearing trees:
 A Fir stump 40" dia., bears N.48°E., 23 lks. dist., with no remaining marks.
 A Fir, turned out, 30" dia., bears S.7°E., 43 lks. dist., mkd. with a healed blaze.
 A Hemlock 27" dia., bears S.81°W., 37 lks. dist., with portions of scribe marks visible on partially healed blaze.
 A Fir 40" dia., bears N.53°W., 78 lks. dist., marked T19S R9W S36 BT on bark.

At the corner point
 Set an iron post, 3 ft. long, 3" dia., 28" in the ground, with brass cap mkd:

T 19 S	R 8 W
T 20 S	S 31
R 9 W	S 6
S 1	T 20 S
1953	

(Cont. Next Page)

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (NW Cor. S. 6, T20-8)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which new bearing trees:

A double Cedar 16" dia., bears N.3¼°E., 81 lks. dist. mkd.
T19S R8W S31 BT.

A Fir 14" dia., bears S.20°E., 87 lks. dist. mkd. T20S R8W
S6 BT.

Wayne Donovan, LS #2553 - May 19, 1993 - C.S. File 63/153-58

Found - 3½" brass cap in good condition.

30" Fir bears S.20°E., 57.1 ft., healed face.

51" Hemlock bears S.82½°W., 24.3 ft., healed face.

46" Fir stump bears N.53½°W., 49.4 ft., no marks.

31" Cedar bears N. 3 3/4°E., 54.2 ft., healed face.

New BT - 15" Hemlock bears S.84½°E., 41.6 ft. blazed and
scribed "T20S R8W S6 BT."

Corner lies on a North facing bench.

BLM dependent resurvey by Edith M Forkner & Jason A
Lightbown, Cadastral Surveyors, under Group #2820, surveyed
Feb./June 2016 - (DCSO records Vol. 59 Page(s) 23530)

The cor. of Tps. 19 & 20 S., R. 8 W., perpetuated by Donovan,
in 1993, monumented with an iron post, 3" dia., firmly set,
projecting 8" above the ground, with a brass cap (properly)
mkd.

from which the remains of the original bearing trees

A decayed fir stump, size indeterminate, bears N.53°W.,
51.5 ft., no marks visible.

A hemlock, 63" dia., bears S.81°W., 24.4 ft., with a
healed blaze.

and the BTs mkd. by Tillman, et al., in 1953-54

A double-trunk cedar, 35" dia., bears N.3¼°E., 52.6 ft.,
with a healed blaze. (Record, 53.5 ft.)

A fir stump, 33" dia., bears S.20°E., 57.4 ft., with a
healed blaze and an aluminum nail at the base on left
side center.

and the bearing tree mkd. by Donovan

A hemlock, 27" dia., bears S.84½°E., 41.4 ft., with a
healed blaze.

The geographic position in NAD 1983 (2011)

Latitude: 43°51'48.66" N. Longitude: 123°42'11.85" W.

Jerry Estabrook - For: Roseburg Resources Co. - 8/2020 -
M177-40

Found - A 3" iron pipe with 3½" brass cap mkd "T20S R9W S1
T19S R8W S31 S6 T20S 1953" per 1953 BLM survey.

Continued next page

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (NW Cor. S. 6, T20-8)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A 45" double trunk cedar with healed face and tag bears N.03°30'E., 52.6'.
A rotten fir stump with no visible marks bears N.53°W., 51.5'.
A 27" Hemlock with healed face and tag bears S.84°30'E., 41.4'.
A 33" Fir stump with healed face and tag bears S.20°E., 57.4'.
A 63" Hemlock with healed face and tag bears S.81°W., 24.4'.
Fd BOs - An aluminum post bears West 1.3'.
An aluminum post bears East 1.4'.
LAT. AND LONG. PER GARMIN ETREX HAND HELD GPS - NOT SURVEY
GRADE: N: 43°51'48.9" W: 123°42'12.0"