

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 542-3)

Set post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., mkd: 1/4 S on N face; from which
 A Fir, 14" dia., bears N.41°W., 26 lks., mkd: 1/4 S BT
 A Fir, 10" dia., bears S.49 1/2°E., 20 lks., mkd: 1/4 S BT

Eugene Dist. of BLM - Transit and tape survey by Wayne Tinglum, Mark Lichtenthaler, Larry Smith & Michael Bilderback - Completed Oct. 1974 - M 57-31

Set - 3/4" iron rod from orig. BTs.

BLM dependent resurvey by Lester E. Fisher & David W. Mattson, Cadastral Surveyors, under Group #'s 1000 & 1029, Surveyed Jan/Dec. 1980 - (DCSO records Vol. 46 Pages 17721-2)

The 1/4 sec. cor. of secs. 7 & 18, determined from the orig. BTs:
 A Fir, 28" dia., bears S.49 1/2°E., 20 lks., with healed double blaze.
 A Fir, 35" dia., bears N.41°W., 26 lks., with healed double blaze.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked:
 T19S R8W
 1/4 S 7
 S 18
 1980
Set a 6 ft. steel fence post alongside the iron post.

Corey Woodruff - For: Plum Cr. Timberland - 5/2009 - M159-30

Found - 1980 BLM BCIP
 38" D.Fir stump bears N.41°W., 14.7' to face.
 30" D.Fir stump bears S.53°E., 12.5' to face.
BTs mkd- 8" D.Fir bears S.45°W., 8.0' (carved W/"X"; not scribed)
 8" D.Fir bears N.85°E., 13.2' (carved W/"X"; not scribed)