

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 540-41)

-----  
Set post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd: ¼ S on W face; from which

A Fir, 12" dia., bears N.46 2/3°E., 179 lks., mkd: ¼ S BT  
No trees in limits on W side; dug pits, 18x18x12 ins. W. of post, 5½ ft. dist. and raised a mound of earth, 2 ft. high, 4½ ft. base, around post.

-----  
Eugene Dist. of BLM - Transit and tape survey by Wayne Tinglum, Mark Lichtenthaler, Larry Smith & Michael Bilderback - Completed Oct. 1974 - M 57-31

-----  
Set - 3/4" iron rod from which:

An 18" Fir, bears S.22 3/4°W., 28.0 ft.

A 26" Fir, bears S.24½°E., 41.4 ft.