

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 530)

Set post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., mkd: 1/4 S on W face; from which

A Fir, 12" dia., bears N.37°E., 31 lks., mkd: 1/4 S BT

A Fir, 24" dia., bears N.73 1/2°W., 22 lks., mkd: 1/4 S BT

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12940-41)

Point for the 1/4 sec. cor. of secs. 16 & 17 as determined from the orig. BTs:

A Fir, 19" dia., bears N.37°E., 31 lks., mkd. with an old blaze on SW face.

A Fir, 32" dia., bears N.73 1/2°W., 22 lks., with old blaze on SE face.

At the corner point

Set an iron post, 3' long, 1" dia., 26" in the ground, with brass cap marked:

1/4
S 17 | S 16
1952

from which

A Fir, 36" dia., bears N.86 1/2°E., 94 lks., mkd: 1/4 S16 BT.

An Alder, 10" dia., bears S.64°W., 40 lks., mkd: 1/4 S BT.

Ron Rice, NW Land Surveying - Sept. 2013 - C.S. File 65/80-4

Condition Report only

Found - 1952 2 1/2" GLO brass cap w/the following accessories:
Fir, 19" dia., bears N.37°E., 31 lks., mkd. with an old blaze on SW face. (Fd 27" Fir w/healed face)
Fir, 32" dia., bears N.73 1/2°W., 22 lks., with old blaze on SE face (Fd 32" Fir stump w/healed face)
Fir, 36" dia., bears N.86 1/2°E., 94 lks., mkd: 1/4 S16 BT. (Fd 66" Fir with healed face)
Alder, 10" dia., bears S.64°W., 40 lks., mkd: 1/4 S BT. (Missing)

Note - Corner has steel post adjacent to it. All live BTs have red painted bands and yellow tags.
Compass Declination 16° East

Robert Cook - For: Oxbow Timber 1 LLC - 2/2018 - M174-18

Found - 1952 GLO brass cap up 20" on north slope with steel post south 1.5'. Monument lies on the west side of a clear cut. continued next page

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>20" D.Fir N.37°E., 20.5 ft. with healed face, tag and paint. 32" D.Fir N.73°30'W., 14.5 ft. with healed face, tag and paint. 66" D.Fir stump N 86°30'E 62.0'.</p>
<p>Robert A. Cook - For: Oxbow Timber 1 LLC - 4/2020 - M177-1 ----- Found - 1952 GLO brass cap up 20" on north slope with steel post south 1.5'. Monument lies on the west side of a clear cut. 20" D.Fir N.37°E., 20.5 ft. with healed face, tag and paint. 32" D.Fir N.73°30'W., 14.5 ft. with healed face, tag and paint. 66" D.Fir stump N.86°30'E., 62.0'.</p>