

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 515)

-----  
et post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., mkd: 1/4 S on W face; from which

A Fir, 12" dia., bears S.69 1/2°W., 57 lks., mkd: 1/4 S BT.

A Fir, 18" dia., bears S.24°E., 46 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #'s 350 & 417, Surveyed Sept/Oct 1958 - (DCSO records Vol. 29 Page(s) 12328)

-----  
The 1/4 sec. cor. of secs. 22 & 23, determined at the record bearing & distance from each of the orig. BTs, as follows:

A burned Fir snag, 16" dia., bears S.24°E., 46 lks., with scribe marks 1/4 S BT visible on unburned face of blaze.

The decayed remains of a Fir stump, size indeterminate, bears S.69 1/2°W., 57 lks., with no marks remaining.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T19S R8W

1/4

S 22 S 23

1958

from which new BTs:

A Fir, 32" dia., bears N.88 1/2°E., 22 lks., mkd: 1/4 S23 BT.

A fir, 12" dia., bears N.77 1/4°W., 37 lks., mkd: 1/4 S22 BT.

Fd. OK by M. Krush - 11/11/1982 M93-36

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.