

PRIMARY CORNER DESCRIPTION Cor. Secs 10, 11, 14, & 15

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Lane Co. Surveyor's Office - M. Blomme - Crew: Bruce Bothel & Stuart Duce - Jan. 26, 2015 (added 10/20/2021 to DCSO records) - C.S. 65/109-32

Found - 2½" I. Post with ¾" BC 10" above ground. (1958 BC properly mkd)

- 1891: 30"x40' tall fir snag, healed face bears S.22¼°E., 15.0' to center (S.22¼°E., @ 15.8')
- 1958: 30"x30" tall fir snag with marks bears N.17°E., 34.8' to center (N.16¼°E., 34.3')
- 1958: 30"x60" tall fir snag with marks bears S.61¾°W., 48.1' to center (S.61¾°W., 46.9')
- 1958: 29"x20" tall fir snag with marks bears N.86°W., 40.2' to center (N.86°W., 39.6')

New -

- 8" D.Fir marked "CSBT" N.4¾°E., 13.7' to center.
- 5/8"x30" rebar w/2" alum cap "LCS0-RP1-2015" 4" below ground N.78½°E., 20.08'
- 5/8"x30" rebar w/2" alum cap "LCS0-RP2-2015" 4" below ground S.2½°E., 17.53'
- 16" D.Fir marked "CSBT" S.75°W., 8.0' to center.

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2846, surveyed June 2016 - Nov. 2016 - (DCSO records Vol. 59 Page(s) 23805-6)

The cor. of secs. 10, 11, 14, and 15, perpetuated by Rice, in 2015; further perpetuated by Blomme, in 2015, monumented with an iron post, 2½" dia., firmly set, projecting 8" above ground, with a brass cap (properly) mkd. from which the remains of the BTs reported by Brooks in 1958

- A fir snag, 35" dia., bears N.16¼°E., 34.3 ft., with illegible scribe marks visible on partially healed blaze.
- A fir snag, 26" dia., bears S.22¼°E., 15.8 ft., with a healed blaze, (Original)
- A decayed fir snag, 24" dia., bears S.61¾°W., 46.9 ft., with a healed blaze.
- A decayed fir snag, 22" dia., bears N.86°W., 39.6 ft., with a healed blaze.

and a bearing tree mkd. by Rice

- A fir, 8" dia., bears N., 13.7 ft., with illegible scribe marks visible on partially healed blaze.

and accessories mkd. by Blomme

- An iron rod, 5/8" dia., firmly set, with top flush with the surface of the ground, bears N.77°55'54"E, 20.02 ft., with an aluminum cap mkd. LANE COUNTY SUVEYORS OFFICE RP1 2015.

Continued next page

TOWNSHIP 18 RANGE 08 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An iron rod, 5/8" dia., firmly set, with top flush with the surface of the ground, bears S.4°14'29"E, 17.49 ft. with an aluminum cap mkd. LCS0 RP2 2015.
A fir, 14" dia., bears S.72½°W., 7.8 ft., with scribe marks BT visible on partially healed blaze.
and a new BT
A fir, 8" dia., bears N.30°W., 26.4 ft., mkd. T19S R8W S10 BT.
A galvanized fence post is alongside the cor.
A search was made for all original line trees on the line resurveyed bet. secs. 14 and 15 and none were recovered.

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.