

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T20-8

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 2 Page(s) 463-64)

 Set post 6" dia., 4 ft. long, with marked stone 12" in ground for cor. to secs. 35, 36, 1 & 2, marked T19S S36 on NE.; R8W S1 on SE.; T20S S2 on SW.; S35 on NW. faces, with 5 notches on W. & 1 on E. edges; from which
 Fir 12" dia., bears N.42°E., 21 lks. dist., mkd. T19S R8W S36 BT.
 Fir 8" dia., bears S.41°E., 19 lks. dist. mkd. T20S R8W S1 BT.
 Fir 8" dia., bears S.55°W., 47 lks. dist. mkd. T20S R8W S2 BT.
 Fir 10" dia., bears N.77°W., 33 lks. dist. mkd. T19S R8W S35 BT.

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 507)

 At the sec.cor., where finding lonly the burnt end of the original post, I set a new post, 4½ ft. long, 4" sq., 24" in ground, mkd. T19S S36 on NE.; R8W S1 on SE.; T20S S2 on SW.; S35 on NW. faces, with 5 notches on W. and 1 notch on E. edges; from which the original bearing trees are found as described by Wright.

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12913-14)

 The point for the sec. cor., at proportionate distance; there is no remaining evidence of the orig. corner.
 Set an iron post 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:

T19S	R8W
S 35	S 36
S 2	S 1
T20S	
1952	

from which
 A Fir 22" dia., bears N.52°E., 23 lks. dist. mkd. T19S R8W S36 BT.
 Fir 12" dia., bears S.69½°E., 35 lks. dist. mkd. T20S R8W S1 BT.
 A Fir 11" dia., bears S.68¼°W., 28 lks. dist. mkd. T20S R8W S2 BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T20-8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A Fir 15" dia., bears N.49½°W., 54 lks. dist. mkd. T19S R8W S35 BT.

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16715-16)

The Sec. Cor., monumented with an iron post 2" dia., firmly set, projecting 8" above ground, with brass cap mkd. in 1952, from which bearing trees mkd. in 1952

A Fir 23" dia., bears N.57°E., 23 lks. dist., healed blaze. (Rec. N.52°E.)

A Fir 15" dia., bears S.69½°E., 38 lks. dist., healed blaze. (Rec. 35 lks.)

A Fir 15" dia., bears S.68¼°W., 28 lks. dist., healed blaze.

A Fir 20" dia., N.49½°W., 54 lks. dist., healed blaze.
Set a 6 ft. steel fence post alongside the iron post.

Fd. OK, Dec. 1986 by Skinner - M 103-6

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23179-80)

The cor. of secs. 1, 2, 35, 7 36, monumented with an iron post, 2" dia., firmly set, projecting 12" above ground, with a brass cap(properly) mkd.

from which the remains of the BTs mkd. by Lytle & Norseth in 1952

A decayed fir snag, 23" dia., bears N.57°E., 15.2 ft., with a healed blaze.

A roothole bears S.69½°E., 25.1 ft., alongside of which is a decayed rootwad, no marks visible.

A decayed fir high stump, 17" dia., bears S.66¼°W., 18.5 ft., with a healed blaze & X at breast height. (Record, S.68¼°W.)

A decayed fir snag, 24" dia., bears N.49½°W., 33.7 ft., with a healed blaze. (Record, 35.6 ft.)

and new bearing trees

A fir, 6" dia., bears N.70°E., 31.7 ft., mkd. T19S R8W S36 BT.

A fir, 11" dia., bears S.83¼°E., 41.1 ft., mkd. T20S R8W S1 BT.

continued next page

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T20-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 6" dia., bears S.27¼°W., 16.2 ft., mkd. T20S R8W
S2 BT.

A fir, 6" dia., bears N.16½°W., 15.0 ft., mkd. T19S R8W
S35 BT.

Corner is located in an area of young second growth, with a red steel fence post with an International Paper property sign and a yellow steel fence post alongside the cor.