

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 508)

-----  
A stone, 12x8x15 feet above the ground, having a corner at the exact point which I mark with a cross for cor. to secs. 35, 36, 25, & 26 and mark the E. and S. edges with 1 notch each and raised a mound of stone alongside, there being no trees in limits.

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12919-20)

-----  
Point for the cor. of secs. 25, 26, 35, & 36, marked with a cross (X) on the projecting corner of a boulder in place, 15x12x8 feet above ground; other marks indistinct.

At the corner point, under the projecting corner of the boulder.

Set an iron post, 3' long, 2" dia., 18" in the ground to solid rock and in a mound of stone to top, with brass cap mkd:

T19S R8W	
S 26	S 25
S 35	S 36
1952	

from which

A Fir, 25" dia., bears N.49°E., 19 lks., mkd: T19S R8W S25 BT.

A Fir, 20" dia., bears S.44°E., 29 lks., mkd: T19S R8W S36 BT.

A Fir, 17" dia., bears S.21½°W., 21 lks., mkd: T19S R8W S35 BT.

A Fir, 15" dia. bears N.47°W. 74 lks. mkd: T19S R8W S26 BT

BLM dependent resurvey by Lester E. Fisher & David W. Mattson, Cadastral Surveyors under Group # 1000 & 1029, Surveyed Jan/Dec. 1980 - (DCSO records Vol. 46 Pgs 17699-700)

-----  
The cor. of secs. 25, 26, 35, & 36, monumented with an iron post, 2" dia., firmly set, projecting 10" above ground, under protruding SE lip of boulder, 15x12x8 ft above ground, no marks remaining with properly marked brass cap, from which the remains of BTs mkd. by Lytle and Norseth:

A Fir, 33" dia., bears N.49°E., 19 lks., with healed blaze.

A root hole, bears S.44°E., 29 lks., with a down fir, 24" dia., alongside, with healed blaze.

(Cont. next page)

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A root hole, bears S.47°W., 74 lks., with a down fir, 20" dia., alongside, with healed blaze. (Rec. S.21½°W., 21 lks.)  
A Fir snag, 21" dia., bears N.21½°W., 21 lks., with healed blaze. (Rec. N.47°W., 74 lks.)  
and new BTs  
A Fir, 30" dia., bears S.64°E., 50 lks., mkd: T19S R8W S36 BT.  
A Cedar, 16" dia., bears S.26°W., 96 lks., mkd: T19S R8W S35 BT.  
A Fir, 25" dia., bears N.41½°W., 42 lks., mkd: T19S R8W S26 BT.

Bob Cook - For: Roseburg Forest Products - 2/2020 - M176-52  
-----  
Found - 1952 1½" pipe with 2½" brass cap up 11" and 1.8 ft. East of a large boulder. We set a steel post 1 ft South. Overgrown road lies West about 100 ft.  
35" D.Fir N.49°E., 19 lks. with healed face, tag and paint.  
30" D.Fir snag S.64°E., 50 lks. with healed face.  
25" Cedar S.26°W., 96 lks. with healed face, tag and paint