

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24 only, T19-10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 19, 1899 - (DCSO records Vol. 1 Page(s) 271)

-----  
Set an Alder post 3 ft. long, 4" sq., 24" in the ground for the cor. of secs. 13 & 24, marked T19S S24 on SW.; and R10W S13 on NW. faces, with 3 notches on N. & S. edges; from which  
An Alder 8" dia., bears N.25°W., 12 lks. dist. mkd. T19S R10W S13 BT.  
An Alder 4" dia., bears S.80°W., 27 lks. dist. mkd. T19S R10W S24 BT.

From this cor. the old cor. bears E. 9 lks. dist., I destroy it.

\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13033)

-----  
Point for the cor. of secs. 13 & 24 only, at proportionate distance; there is no remaining evidence of the original stone.

Set an iron post 28" long, 2½" dia., 22" in the ground with brass cap mkd. T 19 S T 19 S

S 13  
S 24 S 19  
R 10 W R 9 W  
1958

from which

A Fir 45" dia., bears S.38°W., 124 lks. dist. mkd. T19S R10W S24 BT.

A Fir 40" dia., bears N.55°W., 70 lks. dist. mkd. T19S R10W S13 BT.

Cor. Fd. OK and used in BLM survey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 - (DCSO records Vol. 37 Page(s) 15430)

BLM Resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/May 1991 - (DCSO records Vol. 49 Page(s) 18768-69)

-----  
The cor. of secs. 13 & 24 only, monumented with an iron post 2½" dia., firmly set, projecting 3" above ground with brass cap mkd. in 1958, (Cont. Next Page)

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 100369

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24 only, T19-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of bearing trees mkd. by Tillman,etal  
A root hole, bears S.38°W., 124 lks. dist., lying  
alongside is a Fir stump, 45" dia., face area buried.  
A Hemlock stump 40" dia., bears N.55°W., 64 lks. dist.,  
with scribe marks T19S R10W S19 visible on partially  
healed blaze. (Rec. Fir, 70 lks.)  
and new bearing trees:  
An Alder 16" dia., bears S.64°W., 58 lks. dist. mkd. T19S  
R10W S24 BT on the bark.  
A Fir 5" dia., bears N.4°W., 161 lks. dist. mkd. X BT.