

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 418)

A Fir, 7" dia., for 1/4 sec. cor., I mark 1/4 S6 on N & 7 on S sides; from which
A Fir, 8" dia., bears N.24°E., 15 lks., mkd: 1/4 S BT.
A Fir, 10" dia., bears S.66°E., 15 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13066)

The 1/4 sec. cor. of secs. 6 & 7, located in the stump hole of an uprooted Fir, 10" dia., with fragmentary scribe marks visible on the fallen trunk, from which the orig. BTs:

A Fir snag, 12" dia., bears N.24°E., 15 lks. with a healed blaze.
A Fir stump, 10" dia., bears S.73 1/2°E., 15 lks., with fragmentary scribe marks visible on broken blaze. (Rec. bearing S.66°E.)

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap marked:

S 6
1/4
S 7
T19S R9W
1958

from which
A Fir, 28" dia., bears N.22°E., 38 lks., mkd: 1/4 S6 BT.
A Hemlock, 13" dia., bears S.29°E., 86 lks., mkd: 1/4 S7 BT.

Clyde Mulkins & Ronald Stuntzner - For: US Forest Service
March 1983 - M 94-21 A-C

Found - BLM BCIP mkd: 1/4 S6 S7 T19S R9W 1958, from which
12" D.Fir snag bears N.24°E., 9.6 ft. (Orig)
27" D.Fir snag bears N.22°E., 25.3 ft., w/healed face. 1958
25" Hemlock bears S.27°E., 56.6 ft., open face - scribe visible. 1958
19" Hemlock bears S.68°E., 13.7 ft., w/healed face.

Fd. ok by D. Baker, Sept. 1988 - M 107-1

(Cont. next page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/May 23, 1991 - (DCSO records Vol. 49 Page(s) 18762)

From the ¼ sec. cor. of secs. 6 & 7, monumented with an iron ost, 2½" dia., firmly set, projecting 4" above ground, with properly marked brass cap.

from which the remains of the orig. BTs:

A Fir snag, 12" dia., 10 ft. high, bears N.24°E., 15 lks., with healed blaze.

A Fir stump, 10" dia., 10" dia., 1 ft. high, bears S.67°E., 15 lks., no marks. (Rec. S.73½°E.)

and the remains of BTs mkd. by Tillman, Holm & Brooks

A Fir snag, 28" dia., 20 ft. high, bears N.22°E., 38 lks., with healed blaze.

A Hemlock, 26" dia., bears S.29°E., 86 lks., with fragmentary scribe marks visible on partially healed blaze.

and a new accessory

A stainless steel post, 28" dia., set 28" in the ground, for a reference monument, bears S.87°26'W., 85.4 lks., with brass cap mkd: RM ¼ S7 56.3 FT. TO COR 1989 and an arrow pointing to the corner.

Daniel Baker - For: Davidson Industries Inc - March 1997 - M 124-48

Found - US BLM Brass Cap 1958

23" Hemlock, S.68°E., 13.8', healed face

30" Hemlock, S.29°E., 57.0', healed face

24" Fir snag, N.23°E., 25.0'.

Set - 27" Hemlock, N.78°W., 37.2', scribed "¼ S6 BT"

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.