

PRIMARY CORNER DESCRIPTION Cor. Secs. 5, 6, 7, & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 417)

A Hemlock, 7" dia., for cor. of secs. 5, 6, 7, & 8, I mark T19S S5 on NE, R9W S8 on SE, S7 on SW, and S6 on NW sides, with 5 notches on S & E sides; from which

- A Hemlock, 7" dia., bears N.67°E., 31 lks., mkd: T19S R9W S5 BT.
- A Hemlock, 9" dia., bears S.55°E., 27 lks., mkd: T19S R9W S8 BT.
- A Hemlock, 7" dia., bears S.15°W., 22 lks., mkd: T19S R9W S7 BT.
- A Hemlock, 7" dia., bears N.79°W., 44 lks., mkd: T19S R9W S6 BT.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13064)

Point for cor. of secs. 5, 6, 7, & 8, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T19S R9W
S 6 S 5
 S 7 S 8
 1958

from which

- A Fir, 12" dia., bears N.83°E., 253 lks., mkd: T19S R9W S5 BT.
- A Fir, 16" dia., bears S.73°E., 211 lks., mkd: T19S R9W S8 BT.
- A Fir, 20" dia., bears S.84°W., 347 lks., mkd: T19S R9W S7 BT.
- A Fir, 12" dia., bears N.25°W., 102 lks., mkd: T19S R9W S6 BT.

Fd. Ok by Mulkins & Stuntzner, March 1983 - M 94-21 A-C
 Fd. ok by D. Baker, Nov. 1991 - M 114-27
 Fd. ok by D. Baker, March 1997 - M 124-48

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.