

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 426)

40.08 chs
A Hemlock, 9" dia., for 1/4 sec. cor., I mark 1/4 S5 on N & 8 on S sides; from which
 A Hemlock, 7" dia., bears N.85°W., 12 lks., mkd: 1/4 S BT.
 A Hemlock, 7" dia., bears S.45°E., 10 lks., mkd: 1/4 S BT.
45.00 chs
Old cor. bears South 12.00 chs., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 31 Page(s) 13065)

Point for 1/4 sec. cor. of secs. 5 & 8, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap marked:
 1/4 S 5
 S 8
 T19S R9W
 1958
from which
 An Alder, 22" dia., bears N.64°W., 84 lks., mkd: 1/4 S5 BT.
 A Fir, 32" dia., bears S.28 1/4°E., 74 lks., mkd: 1/4 S8 BT.

Fd. ok by Mulkins & Stuntzner, March 1983 - M 94-21 A-C
Fd. Ok by D. Baker, Nov. 1991, M 114-27

Lane Co. Surveyor's Office - Bruce Bothel, PLS, Associate Surveyor & Stuart Duce, PLS, Engineering Tech II - Sept. 16, 2015 copied from internet 8/2/2016 - C.S. File 65/93-26

Found - At the corner position fd a 1958, 3 1/4" BLM brass cap (properly mkd) atop a 2 1/2" iron post, 4" above ground.
 A 19" Alder with bark scribes, bears N.64°W., 55.8' to center. 1958
 A 46" Fir w/healed face, bears S.28 1/4°E., 49.1' to center. 1958
New BTs- 10" Hemlock, mkd "CSBT" N.28 1/2°E., 27.2' to center.
 12" Hemlock, mkd "CSBT" S.84°W., 23.0' to center.
continued next page

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - BTs: Distance shown is to an aluminum nail set at side/center of live trees.
Basis of bearing - N.64°W., from brass cap to 1958
Geographic map location: for finding the corner area
- not of survey grade accuracy NAD 83/91 values:
LAT: N.43°56'39.7" LONG. W.123°47'51.2"