

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 32 & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 418-19)

The ¼ sec. cor., established on former survey*, which is a post, 3 ft. long, 3" sq., set 24" in the ground, marked ¼ S32 on W & 33 on E faces; from which

A Fir, 7" dia., bears N.10°E., 13 lks., mkd: ¼ S BT.

An Alder, 6" dia., bears S.15°W., 35 lks., mkd: ¼ S BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15451)

Point for ¼ sec. cor. of secs. 32 & 33, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

¼
S 32 S 33
T19S R9W
1969

from which

A Cedar, 8" dia., bears S.33°E., 67½ lks., mkd: ¼ S33 BT.

A Maple, 12" dia., bears N.40½°W., 58 lks., mkd: ¼ S32 BT.