

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 419)

The cor. of secs. 28, 29, 32, & 33, established on former survey*, which is a post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, marked T19S S28 on NE, R9W S33 on SE, S32 on SW and S29 on NW faces with 1 notch on S & 4 notches on E edges; from which

- A Chittem, 6" dia., bears N.16°E., 20 lks., mkd: T19S R9W S28 BT.
- A Fir, 5" dia., bears S.27°E., 27 lks., mkd: T19S R9W S33 BT.
- A Fir, 5" dia., bears S.83°W., 100 lks., mkd: T19S R9W S32 BT.
- A Fir, 6" dia., bears N.75°W., 37 lks., mkd: T19S R9W S29 BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15452)

Point for cor. of secs. 28, 29, 32, & 33, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T19S R9W
S 29 S 28
S 32 S 33
1969

from which

- A Maple, 35" dia., bears N.68°E., 48 lks., mkd: T19S R9W S28 BT.
- A Hemlock, 17" dia., bears S.6°E., 88½ lks., mkd: T19S R9W S33 BT.
- A Fir, 65" dia., bears S.57°W., 56 lks., mkd: T19S R9W S32 BT.
- A Fir, 36" dia., bears N.81°W., 25 lks., mkd: T19S R9W S29 BT.