

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 420)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S29 on W and 28 on E faces; from which
A Fir, 6" dia., bears N.71°E., 31 lks., mkd: ¼ S BT.
A Fir, 7" dia., bears N.4°W., ? lks., mkd: ¼ S BT.
Old cor. bears West 16 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15454)

Point for ¼ sec. cor. of secs. 28 & 29, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

¼
S 29 S 28
T19S R9W
1969

from which
A Maple, 20" dia., bears S.48°E., 33 lks., mkd: ¼ S28 BT.
A Fir, 45" dia., bears S.65°W., 89 lks., mkd: ¼ S29 BT.