

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Cor. Secs. 20, 21, 28, & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 420-21)

Set a sandstone, 12x8x8 ins., 8" in the ground, for cor. of secs. 20, 21, 28, & 29, marked with 2 notches on S & 4 notches on E edges; from which

- A Fir, 6" dia., bears N.50°E., 20 lks., mkd: T19S R9W S21 BT.
- A Fir, 6" dia., bears S.70°E., 80 lks., mkd: T19S R9W S28 BT.
- A Fir, 6" dia., bears S.15°W., 50 lks., mkd: T19S R9W S29 BT.
- A Fir, 10" dia., bears N.10°W., 18 lks., mkd: T19S R9W S20 BT.

Old cor. bears S.75°E., 10 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15454)

Point for cor. of secs. 20, 21, 28, & 29, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T19S R9W
S 20 S 21
S 29 S 28
1969

- from which
- A Cedar, 13" dia., bears N.38°E., 69 lks., mkd: T19S R9W S21 BT.
 - A Hemlock, 22" dia., bears S.69°E., 52 lks., mkd: T19S R9W S28 BT.
 - A Maple, 20" dia., bears S.64°W., 33 lks., mkd: T19S R9W S29 BT.
 - An Alder, 15" dia., bears N.58°W., 27 lks., mkd: T19S R9W S20 BT.