

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Cor. Secs 16, 17, 20, & 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 422)

Set a sandstone, 12x8x6 ins., 8" in the ground, for cor. to secs. 16, 17, 20, & 21, marked with 3 notches on S & 4 notches on E edges; from which
A Fir, 6" dia., bears N.13°E., 21 lks., mkd: T19S R9W S16 BT.
A Fir, 4" dia., bears S.8°E., 30 lks., mkd: T19S R9W S21 BT.
A Fir, 6" dia., bears S.20°W., 15 lks., mkd: T19S R9W S20 BT.
A Fir, 8" dia., bears N.28°W., 20 lks., mkd: T19S R9W S17 BT.

Old cor. bears East 20 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15456)

Point for cor. of secs. 16, 17, 20, & 21, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T19S	R9W
S 17	S 16
S 20	S 21
1969	

from which
A Fir, 13" dia., bears N.43°E., 17 lks., mkd: T19S R9W S16 BT.
A Fir, 10" dia., bears S.57½°E., 29 lks., mkd: T19S R9W S21 BT.
A Fir, 13" dia., bears S.41°W., 26 lks., mkd: T19S R9W S20 BT.
A Fir, 13" dia., bears N.66°W., 22 lks., mkd: T19S R9W S17 BT.

Fd Ok by E. Alvarado, USFS - 12/6/1979 - C.S. File 60/34-23