

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 423)

-----

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S17 on W and 16 on E faces; from which  
A Fir, 5" dia., bears N.60°E., 29 lks., mkd: ¼ S BT.  
A Fir, 5" dia., bears S.52°W., 40 lks., mkd: ¼ S BT.  
Old cor. bears East 15 lks., I destroy it.  
\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15458)

-----

Point for ¼ sec. cor. of secs. 16 & 17, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 6" in the ground, to solid rock, in a mound of stone, 5 ft. base, to top, with brass cap marked:

¼  
S 17 | S 16  
T19S R9W  
1969

from which  
A Fir, 30" dia., bears N.26°E., 39 lks., mkd: ¼ S16 BT.  
A Hemlock, 25" dia., bears S.69°W., 87 lks., mkd: ¼ S17 BT.

Fd. Ok by E. Alvarado, USFS C.S. File 60/34-26