

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 9

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 424-25)

36.00 chs
Old cor. bears East 2.00 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.
40.00 chs
A Fir, 14" dia., for ¼ sec. cor., I mark ¼ S8 on W & 9 on E sides; from which
 A Fir, 14" dia., bears N.73°E., 32 lks., mkd: ¼ S BT.
 A Fir, 8" dia., bears S.23°W., 24 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13059-60)

From the ¼ sec. cor. of secs. 8 & 9, mkd. by a Fir 25" dia., plainly blazed & healed, from which the orig. BTs:
 A Fir, 22" dia., bears N.73°E., 32 lks., blazed & healed.
 A Fir snag, 10" dia., bears S.23°W., 24 lks., blazed & healed.
and a new BT
 A Fir, 28" dia., bears N.80°W., 97 lks., mkd: ¼ S8 BT.

Fd. & used on BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15460)

Fd. Ok by D. Baker - Nov. 1991 - M 114-27

Fd. Corner tree & BTs as described on M114-27, 4/2016 by T. Hostetter, M172-22