

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 427)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S28 on N and 33 on S faces; from which
 A Fir, 6" dia., bears N.37°E., 40 lks., mkd: ¼ S BT.
 A Fir, 6" dia., bears S.42°W., 33 lks., mkd: ¼ S BT.
Old cor. bears South 4 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15452-53)

Point for ¼ sec. cor. of secs. 28 & 33, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

¼ S 28
 S 33
T19S R9W
1969

from which
 A Fir, 20" dia., bears N.45½°W., 20 lks., mkd: ¼ S28 BT.
 A Maple, 14" dia., bears S.12°E., 26 lks., mkd: ¼ S33 BT.