

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 430)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S16 on N and 21 on S faces; from which
A Fir, 12" dia., bears N.12°E., 40 lks., mkd: ¼ S BT.
A Fir, 12" dia., bears S.80°W., 26 lks., mkd: ¼ S BT.
Old cor. bears S.25°E., 15 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15457)

Point for ¼ sec. cor. of secs. 16 & 21, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

¼ $\frac{S\ 16}{S\ 21}$
T19S R9W
1969

from which
A Fir, 15" dia., bears N.45°E., 38 lks., mkd: ¼ S16 BT.
A Fir, 15" dia., bears S.4°E., 19 lks., mkd: ¼ S21 BT.

Fd BC & 2 BTs by Marcus Helm - 7/2024 - M184-9