

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 434)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S9 on N and 16 on S faces; from which
 A Fir, 4" dia., bears N.21°E., 12 lks., mkd: ¼ S BT.
 A Fir, 7" dia., bears S.10°W., 50 lks., mkd: ¼ S BT.
 Old cor. bears S.75°E., 16 lks., I destroy it.
 * 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15459)

Point for ¼ sec. cor. of secs. 9 & 16, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

$\frac{1}{4} \quad \frac{S \quad 9}{S \quad 16}$
 T19S R9W
 1969

from which
 A Hemlock, 20" dia., bears N.11 3/4°W., 30 lks., mkd: ¼ S9 BT.
 A Fir, 28" dia., bears S.15°E., 57 lks., mkd: ¼ S16 BT.