

PRIMARY CORNER DESCRIPTION Sec Cor for 33 & 34 only, (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 14, 1899 - (DCSO records Vol. 44 Page(s) 17054)

Set a Fir post 3 ft. long, 4" sq., 24" in the ground for cor. of sec. 33 and 34, marked T19S S34 on NE. and R9W S33 on NW. face, with 3 notches on E. and W. edges, from which
A Fir 4" dia., bears N.80°E., 5 lks. dist. mkd. T19S R9W S34 BT.
A Fir 4" dia., bears N.60°W., 12 lks. dist. mkd. T19S R9W S33 BT.
The old cor. bears E. 9 lks. dist. I destroy it.

GLO resurvey by Fred Mensch, U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 377)

(Apportioned distance) Set an iron post 3 ft. long, 2" dia., 27" in the ground, for re-established cor. of secs. 33 and 34, T19S R9W., with brass cap mkd:

T19S	R9W
S33	S34
T20S	R9W
S 4	1921

from which
An Alder 12" dia., bears N.20°E., 20 lks. dist., mkd. T19S R9W S34 BT.
A Fir 30" dia., bears N.31°W., 36 lks. dist. mkd. T19S R9W S33 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew June 19, 1969 - C.S. File 53/66-50

Found - 1921 GLO brass cap on broken concrete filled I.P. in place.
30" now 36" Fir N.81°W., 23.8 ft. (Rec. N.31°W.)
Dead, shows good scar.
No trace of NE. BT found.
Set Brass cap at cor. mkd: County Surveyors Office

T 19	S
S 33	S 34
	R9W
	1969

New BT - 10" Maple N.45°W., 32.6 ft. mkd. T19S R9W S33 CS BT
No other trees close to NE.
Cor. lies on very steep southerly slope on E-W cutting line.
Clear cut to South.

(Cont. Next Page)

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec Cor for 33 & 34 only, (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Fd. OK and used in BLM survey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 - (DCSO records Vol. 37 Page(s) 15440)

Ronald L Rice - For: Oxbow Timber 1 LLC - 4/2016 - M170-76

Found - Douglas County brass cap dated 1969 (1921 GLO cap and pipe adjacent) with the following accessories:

Record 30" Fir bearing N.81°W., - missing

13" Maple bears N.45°W., 32.6' - healed face

New BTs- 16" D.Fir bears N.53°E., 5.6' - blazed, scribed T19S
R9W S34 BT

18" D.Fir bears S.29°E., 13.3' - blazed, scribed X
BT

Steel post adjacent to corner.