TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 428)

---

Set a basalt stone, 16x8x7 ins., 12 ins., in the ground for ¼ sec. cor., mkd: ¼ on W. face; from which
An Alder, 4" dia., bears S.80°E., 12 lks., mkd: ¼ S27 BT.
An Alder, 4" dia., bears S.50°W., 23 lks., mkd: ¼ S28 BT.
Old cor. bears S.86°E., 10 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15443)

---

Point for ¼ sec. cor. of secs. 27 & 28, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

¼
S 28 S 27
T19S R9W
1969

from which
A Fir, 25" dia., bears S.29½°E., 25 lks., mkd: ¼ S27 BT.
A Fir, 35" dia., bears S.61°W., 67 lks., mkd: ¼ S28 BT.