

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 428)

Set a sandstone, 12x8x8 ins., 8 ins., in the ground for cor. of secs. 21, 22, 27 & 28, marked with 2 notches on S and 3 notches on E edges; from which

- A Fir, 5" dia., bears N.70°E., 50 lks., mkd: T19S R9W S22 BT.
- A Fir, 4" dia., bears S.19°E., 44 lks., mkd: T19S R9W S27 BT.
- A Fir, 6" dia., bears S.76°W., 60 lks., mkd: T19S R9W S28 BT.
- A Fir, 6" dia., bears N.37°W., 75 lks., mkd: T19S R9W S21 BT.

Old cor. bears S.60°E., 15 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15443)

Point for cor. of secs. 21, 22, 27 & 28, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T19S R9W
S 21 S 22
S 28 S 27

- from which
- An Alder, 20" dia., bears N.61½°E., 46 lks., mkd: T19S R9W S22 BT.
 - An Alder, 22" dia., bears S.69°E., 23 lks., mkd: T19S R9W S27 BT.
 - A Maple, 18" dia., bears S.48°W., 185 lks., mkd: T19S R9W S28 BT.
 - An Alder, 18" dia., bears N.82°W., 210 lks., mkd: T19S R9W S21 BT.