

PRIMARY CORNER DESCRIPTION Cor. Secs. 15, 16, 21, & 22

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 429)

Set a sandstone, 16x6x6 ins., 12 ins., in the ground for corner of secs. 15, 16, 21, & 22, marked with 3 notches on S and E edges; from which

- A Fir, 6" dia., bears N.18°E., 32 lks., mkd: T19S R9W S15 BT.
- A Fir, 8" dia., bears S.8°E., 20 lks., mkd: T19S R9W S22 BT.
- A Fir, 6" dia., bears S.41°W., 40 lks., mkd: T19S R9W S21 BT.
- A Fir, 12" dia., bears N.70°W., 47 lks., mkd: T19S R9W S16 BT.

Old cor. bears N.4°W., 12 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15445-46)

Point for cor. of secs. 15, 16, 21 & 22, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 21" in the ground, with brass cap marked:

T19S R9W
S 16 S 15
S 21 S 22
1968

- from which
- A Fir, 28" dia., bears N.57°E., 58 lks., mkd: T19S R9W S15 BT.
 - A Fir, 36" dia., bears S.50½°E., 51 lks., mkd: T19S R9W S22 BT.
 - A Fir, 25" dia., bears S.4½°W., 25 lks., mkd: T19S R9W S21 BT.
 - A Fir, 18" dia., bears N.67°W., 85 lks., mkd: T19S R9W S16 BT.