

PRIMARY CORNER DESCRIPTION C C for Secs. 3 & 4 only, T20-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO resurvey by Fred Mensch , U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 377-78)

-----  
 Set an iron post 3 ft. long, 2" dia., 27" in the ground for closing cor. of secs. 3 and 4, with brass cap marked:

T19S R9W  
 -----  
 S34  
 -----  
 S4 | S3  
 T20S | R9W  
 CC  
 1921

from which

A Fir 8" dia., bears S.75°E., 16 lks. dist. mkd. T20S R9W S3 CC BT.

A Chittem 8" dia., bears S.16°W., 70 lks. dist. mkd. T20S R9W S4 CC BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew June 19, 1969 - C.S. File 53/66-51

-----  
 Found 1921 GLO I.P. and brass cap broken. No trace of O.B.Ts. We measure from sec. cor. 33 & 34 of T19S R9W to locate pipe. Record dist. is 335.3 ft. We make it 332.0 ft. on brg. of N.86°E. S.86°W at cor. point in place of old pipe. Set 1" I.P. and brass cap mkd. County Surveyors Office

T 19 S R 9 W  
 -----  
 C. C.  
 -----  
 S4 | S3  
 T 20 S R 9 W  
 1969

New BT - 48" D.Fir, stump, S.27°E., 45.6 ft. mkd. CC S3 CS BT  
 No other trees or stumps available. This cor. lies on very steep SW. slope.

Douglas Co. Surveyors Office - L.E. Monrean; P.Earle; J.H. Cook, crew - Jan. 20, 1976 - C.S. File 59/2-9

-----  
 Found - 38" (rec. 48") dia. Fir stump. Stump is rotted, partial scribing visible "CC S3 BT". Stump bears S.27°E., 45.6 ft.

Brass cap not found.

Set brass cap at closing cor. stamped: T19S R9W

-----  
 S 34  
 -----  
 S 4 | S 3  
 C C  
 T21S R9W

(Cont. Next Page)

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 406100

PRIMARY CORNER DESCRIPTION C C for Secs. 3 & 4 only, T20-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Set spike in 43" dia Fir stump. Spike bears S.39°W., 118.4 ft., spike stamped "B.O."  
There are no suitable trees for scribing in the southerly quadrants. Cor. falls in a steep slide area.

Ronald L Rice - For: Oxbow Timber 1 LLC - 4/2016 - M170-76  
-----

Found - Douglas Co. brass cap set in 1976 with the following accessories:

38" D.Fir stump bears S.27 E., 45.6' - scribing visible.

43" D.Fir stump with spike marked "BO" bears S.39 W., 118.4'

New BTs- 15" D.Fir bears N.36 E., 13.5' - blazed, scribed X BT

13" twin maple bears S.16 E., 39.0' - blazed, scribed T20S R9W S3 CC BT

15" D.Fir bears S.21 W., 16.8' - blazed, scribed T20S R9W S4 CC BT

Steel post adjacent to corner