TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 34; & 3, T20-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Nathaniel Martin, under Contract 599, dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 215)

Set post 3½ ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face; from which

Fir 12" dia., bears N.10°E., 70 lks. dist. mkd. ¼ S BT
Fir 10" dia., bears S.15°W., 80 lks. dist. mkd. ¼ S BT.

GLO resurvey by Fred Mensch , U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 262)

"No corners are found between the cor. of secs. 4, 5, 32 and 33, and the cor. which I accept as cor. of Tps. 19 and 20 S., R 10 W., but I find a fairly continuous line of old blazes extending as far as this Tp. cor., but no further eastward."

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11684)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd: ¼ S 34 / S 3 / 1952

from which

A Hemlock 16" dia., bears N.72°E., 36 lks. dist. mkd. ¼ S34 BT.
A Cedar 60" dia., bears S.78°W., 70 lks. dist. mkd. ¼ S3 BT.

Fd. OK, March 19, 1980 by E. Alvarado - C.S. File 61/6-12
Fd. OK, June 1982 by W. Shull - M 92-29