TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 434)

Set an Alder post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S27 on N and 34 on S faces; from which
An Alder, 5" dia., bears N.20°E., 30 lks., mkd: ¼ S BT.
An Alder, 6" dia., bears S.37°W., 40 lks., mkd: ¼ S BT.
Old cor. bears South 9 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15442)

Point for ¼ sec. cor. of secs. 27 & 34, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

¼ S 27 / S 34
T19S R9W
1969

from which
A Maple, 20" dia., bears N.24°W., 45 lks., mkd: ¼ S27 BT.
A Maple, 17" dia., bears S.13½°E., 45 lks., mkd: ¼ S34 BT.

Fd. Ok by Les Roberts, LS 1039 - 4/3/1984 M96-46 & C.S. File 58/293-4B

Ronald L Rice - For: Oxbow Timber 1 LLC - 4/2016 - M170-76

Found - BLM brass cap dated 1969 with the following accessories:
18" Maple bears S.17°E., 29.7' - healed face.
24" Maple bears N.28°W., 28.0' - healed face.
New BTs- 5" D.Fir bears S.30°W., 8.5' - blazed, scribed X BT
6" D.Fir bears N.53°E., 47.6' - blazed, scribed ¼ S27 BT
Steel post adjacent to corner