TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 435-6)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S22 on N and 27 on S faces; from which
A Fir, 5" dia., bears N.70°E., 16 lks., mkd: ¼ S BT.
A Fir, 4" dia., bears S.60°W., 20 lks., mkd: ¼ S BT.
Old cor. bears N., 16 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15444)

Point for ¼ sec. cor. of secs. 22 & 27, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 21" in the ground, with brass cap marked:

T19S R9W
¼ S 22
S 27
1968

from which
A Fir, 20" dia., bears N.29½°W., 22 lks., mkd: ¼ S22 BT.
A Fir, 17" dia., bears S.27°E., 12 lks., mkd: ¼ S27 BT.