

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 437)

-----  
The ¼ sec. cor., established on former survey\*, which is a post, 3 ft. long, 3" sq., 24" in the ground, mkd: ¼ S15 on N and 22 on S faces; from which

A Fir, 5" dia., bears N.65°W., 35 lks., mkd: ¼ S BT.

A Fir, 6" dia., bears S.99°E., 19 lks., mkd: ¼ S BT.

\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15446-47)

-----  
Point for ¼ sec. cor. of secs. 15 & 22, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 21" in the ground, in a collar of stone, 2 ft. base, to top, with brass cap marked:

T19S R9W

¼ S 15

S 22

1968

from which

A Fir, 23" dia., bears N.19°W., 19 lks., mkd: ¼ S15 BT.

A Fir, 15" dia., bears S.47°W., 65 lks., mkd: ¼ S22 BT.

Corner is located at bottom of descent, slopes S.