

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 438)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S10 on N and 15 on S faces; from which
 A Fir, 6" dia., bears N.76°E., 29 lks., mkd: ¼ S BT.
 An Alder, 6" dia., bears S.20°E., 9 lks., mkd: ¼ S BT.
 Old cor. bears S.80°E., 10 lks., I destroy it.
 * 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15448-49)

Point for ¼ sec. cor. of secs. 10 & 15, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

	T19S	R9W
	¼	<u>S 10</u>
		S 15
		1968

from which
 A Fir, 14" dia., bears N.13°W., 27 lks., mkd: ¼ S10 BT.
 A Fir, 12" dia., bears S.28°E., 38 lks., mkd: ¼ S15 BT.

Les Roberts - For: International Paper - July 1981 - M88-21

Found - Brass cap (BLM)
 14" Fir bears S.23°E., 25.8 ft., (scar visible) 1968
 16" Fir bears N.2½°E., 17.1 ft., (scar visible) 1968

Robert Cook - For: Weyerhaeuser - 2/2019 - M175-24

Found 1968 BLM brass cap up 10" on steep East slope
 25" D.Fir N.2°30'E., 17.1' with scar visible
 18" D.Fir S.23°E., 25.8' with scar visible.