

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 439)

A Fir, 6" dia., for ¼ sec. cor. I mark ¼ S3 on N & 10 on S sides; from which

 A Fir, 6" dia., bears N.1°E., 11 lks., mkd: ¼ S BT.

 A Fir, 9" dia., bears S.66°E., 18 lks., mkd: ¼ S BT.

 Old cor. bears South 3.00 chs.; I destroy it.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13058)

The ¼ sec. cor. of secs. 3 & 10, mkd. by a dead fir, 15" dia., with no marks remaining on decayed blazes, from which the orig. BTs are as follows:

 A Fir, 8" dia., bears N.1°E., 11 lks., with blaze healed & burned. I open and uncover fragmentary scribe marks.

 A Fir, 24" dia., bears S.66°E., 18 lks., plainly blazed & healed.

At the corner point, in place of dead Fir,
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

¼	S	3
	S	10
		1957

from which new BTs:

 A Fir, 12" dia., bears N.13°W., 29 lks., mkd: ¼ S3 BT.

 A Fir, 18" dia., bears S.53°E., 51 lks., mkd: ¼ S10 BT.

S. Kendrick Ford - For: Davidson Industries - April 1975 - 57-9

Set - 2"x36" galv. I. pipe directly under 18" rotted Fir tree which shows old marks for corner and is proper distances from BTs.

 All BTs found.

NO BLM BRASS CAP FOUND.

(Cont. next page)

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Les Roberts - For: International Paper - July 1981 - M88-21

Found - 2" iron pipe at base of 18" live Fir.
Set - Brass cap in the found I.P.
30" Fir bears S.68'E., 11.3 ft. (scar visible) 1899
16" Fir bears S.54'E., 34.8 ft. (scar visible) 1957
18" Fir bears N.12'W., 19.5 ft. (scar visible) 1957

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.