

PRIMARY CORNER DESCRIPTION Cor. Secs. 22, 23, 26, & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 435)

Set a basalt stone, 16x10x6 ins., set 12 ins., in the ground for the cor. of secs. 22, 23, 26, & 27, mkd. with 2 notches on S & E edges; and raised a mound of stone, 2 ft. base, 1½ ft. high, W of cor. No trees within limits.
Old Corner bears West 6 lks; I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15438)

Point for cor. of secs. 22, 23, 26, & 27, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T19S R9W
S 22 S 23
S 27 S 26
1968

from which

- An Alder, 18" dia., bears N.65°E., 13 lks., mkd: T19S R9W S23 BT.
- A Hemlock, 13" dia., bears S.67°E., 17 lks., mkd: T19S R9W S26 BT.
- A Fir, 15" dia., bears S.82°W., 69 lks., mkd: T19S R9W S27 BT.
- A Cedar, 12" dia., bears N.68°W., 29 lks., mkd: T19S R9W S22 BT.