TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 437)

Set a basalt stone, 12x10x8 ins., 8 ins., in the ground for ¼ sec. cor., mkd: ¼ on W. face; from which
A Fir, 4" dia., bears N.10°E., 43 lks., mkd: ¼ S14 BT.
A Fir, 4" dia., bears S.10°W., 7 lks., mkd: ¼ S15 BT.
Old cor. bears S.16°E., 14 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13052)

Point for ¼ sec. cor. at proportionate distance; there is no remaining evidence of the orig. corner.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T19S R9W
¼
S 15 S 14
1958

from which
A Cedar, 20" dia., bears N.72°E., 30 lks., mkd: ¼ S14 BT.
A Fir, 23" dia., bears West 50 lks., mkd: ¼ S15 BT.