

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 437)

Set a basalt stone, 16x10x10 ins., 12 ins., in the ground for cor. of secs. 10, 11, 14, & 15, mkd: with 4 notches on S & 2 notches on E edges; from which

- An Alder, 8" dia., bears N.12°E., 16 lks., mkd: T19S R9W S11 BT.
- An Alder, 9" dia., bears S.70°E., 20 lks., mkd: T19S R9W S14 BT.
- An Alder, 6" dia., bears S.38°W., 29 lks., mkd: T19S R9W S15 BT.
- An Alder, 5" dia., bears N.20°W., 23 lks., mkd: T19S R9W S10 BT.

Old cor. bears S.60°E., 12 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13052-53)

Point for cor. of secs. 10, 11, 14, 15, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T19S	R9W
<u>S 10</u>	<u>S 11</u>
S 15	S 14
1958	

- from which
- A Fir, 20" dia. bears N.60°E., 56 lks mkd: T19S R9W S11 BT
 - A Fir, 21" dia. bears S.39°E., 39 lks mkd: T19S R9W S14 BT
 - A Fir, 13" dia. bears S.44°W., 30 lks mkd: T19S R9W S15 BT
 - A Fir, 15" dia., bears N.42½°W., 27 lks., mkd: T19S R9W S10 BT.

Fd. & used on BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15448)

FD BLM BC on top of ridge at corner of clear cuts by R Cook 2/2019 - M175-24