

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 438)

-----

Set a sandstone, 12x8x8 ins., 8 ins., in the ground for ¼ sec. cor., mkd: ¼ on W. face; from which

A Fir, 6" dia., bears N.70°E., 50 lks., mkd: ¼ S10 BT.

A Fir, 6" dia., bears S.10°W., 60 lks., mkd: ¼ S11 BT.

Old cor. bears East 15 lks., I destroy it.

\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13054)

-----

Point for ¼ sec. cor. of secs. 10 & 11, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

	¼	
S 10		S 11
T19S		R9W
		1958

from which

A Fir, 36" dia., bears N.66°E., 7 lks., mkd: ¼ S11 BT.

A Fir, 35" dia., bears S.46½°W., 91 lks., mkd: ¼ S10 BT.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2500, Surveyed Jan/March 2013 - (DCSO records Vol. 58 Page 23069 & **Survey plat 2014-1**)

-----

The ¼ sec. cor. of secs. 10 & 11, monumented with an iron post, 2½" dia., firmly set, projecting 5" above ground, with a brass cap (properly) mkd.

from which the BTs mkd. by Tillman, Holm, & Brooks in 1957-58

A fir, 48" dia., bears N.66°E., 4.6 ft., with a healed blaze.

A fir, 45" dia., bears S.46½°W., 60.1 ft., with a healed blaze.