

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 443)

Set a basaltstone, 20x12x8 ins., 15 ins., in the ground for 1/4 sec. cor., mkd: 1/4 on N. face; from which
 A Fir, 5" dia., bears N.9°W., 150 lks., mkd: 1/4 S23 BT.
 A Fir, 6" dia., bears S.30°W., 40 lks., mkd: 1/4 S26 BT.
The old cor. bears S.60°E., 9 lks.; I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15438-39)

Point for 1/4 sec. cor. of secs. 23 & 26, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2 1/2" dia., 21" in the ground, with brass cap marked:

T19S R9W
 1/4 S 23
 S 26
 1968

from which
 A Fir, 8" dia., bears N.52 1/2°E., 43 1/2 lks., mkd: 1/4 S23 BT.
 A Fir, 19" dia., bears S.65°E., 47 lks., mkd: 1/4 S26 BT.