

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 444)

Set a basalt stone, 16x10x10 ins., 12 ins., in the ground for 1/4 sec. cor., mkd: 1/4 on N. face; and raised a mound of stone, 2 ft. base, 1 1/2 ft. high, N. of cor. No trees within limits. The old corner bears S.70°E., 15 lks.; I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13050)

Point for 1/4 sec. cor. of secs. 14 & 23, at proportionate distance; there is no remaining evidence of the orig. corner. At the corner point, which falls at the N. edge of the quarry fill.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked:

T19S	R9W
1/4	<u>S 14</u>
	<u>S 23</u>
	1958

from which

- A Fir, 20" dia., bears N.51 1/2°W., 62 lks., mkd: 1/4 S14 BT.
- A Fir, 15" dia., bears S.87 3/4°W., 79 lks., mkd: 1/4 S23 BT.

from this point:

The NE cor. of Roman Nose Lookout building (20 ft. by 14 ft., the long side of which bears E & W) bears S.6°06'E., 12.88 chs.

The NE cor. of a micro-wave station building (20 ft. by 12 ft., long side bears E & W) bears S.1°25'E., 12.61 chs.

Roman Nose Triangulation Station, monumented with an iron bolt, 3/4" dia., set flush with the surface of the ground, bears S.6°08.6'E., 13.306 chs. recently established.

See PLSS number 534400.048 and 544400.048 for the witness corners to the East & the West of this corner.