TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 442)

Set a sandstone, 16x6x6 ins., 12 ins., in the ground for ¼ sec. cor., mkd: ¼ on W. face; from which
A Fir, 6" dia., bears N.16°E., 33 lks., mkd: ¼ S25 BT.
A Fir, 5" dia., bears S.11°W., 22 lks., mkd: ¼ S26 BT.
The old cor. bears East, 20 lks.; I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A.. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15431-32)

Point for ¼ sec. cor. of secs. 25 & 26, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 21" in the ground, with brass cap marked: T19S R9W
¼
S 26 | S25
1968
from which
An Alder, 15" dia., bears N.34½°E., 12 lks., mkd: ¼ S25 BT
A Maple, 10" dia., bears S.26½°W., 25 lks., mkd: ¼ S26 BT.

Jerry Estabrook - For: Roseburg Resources Co. - 4/2021 - M179-32

Found - A 2½" iron pipe with 3¼" brass cap marked "T19S R9W ¼ S26 S25 1968" BLM, set steel post alongside.
New BTs- A 29" Maple, bark scribed "W¼ S25 BT" with X-chop & tag bears N.24°E., 36.7' to a spike at side center.
A 12" Fir face scribed "E¼ S26 BT" with X-chop & tag bears S.44°W., 5.2' to a spike at side center.
A 13" Fir face scribed "E¼ S26 BT" with X-chop & tag bears N.69°W., 16.0' to a spike at side center.
A 13" Fir, face scribed "E¼ S26 BT" with X-chop and tag bears N13'W 23.6' TO A SPIKE AT SIDE CENTER.
LAT and LONG per GARMIN ETREX HAND HELD GPS -
N: 43°53'33.5" W: 123°43'42.6"