

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 446)

Set a basalt stone, 14x10x7 ins. 9 ins. in the ground, for cor. of secs. 11, 12, 13, & 14, marked with 4 notches on S & 1 notch on E edges; and raised a mound of stone, 2 ft. base, 1½ ft. high, W. of corner. No trees within limits.

The old cor. bears East, 17 lks., I destroy it.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13043)

Point for cor. of secs. 11, 12, 13, & 14, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T19S	R9W
<u>S 11</u>	<u>S 12</u>
S 14	S 13
1958	

from which

A Fir, 25" dia., bears N.9°E., 49 lks., mkd: T19S R9W S12 BT.

A Fir, 47" dia., bears S.57°E., 193 lks., mkd: T19S R9W S13 BT.

A Fir, 32" dia., bears S.30°W., 12 lks., mkd: T19S R9W S14 BT.

A Fir, 22" dia., bears N.28°W., 63½ lks., mkd: T19S R9W S11 BT.

Robert Ward - May 2002 filed Oct. 2013 - C.S. File 65/80-7

Found - 2½" dia., brass cap dated 1958
26"x6' fir stump bears N.9°E., 49 lks., "scribing visible"
45"x6' metal capped fir stump bears S.57°E., 193 lks., "scribing visible"
26"x8' fir stump bears S.30°W., 12 lks. "scribing visible"

22" fir is missing
New - 10" fir bears S.43°W., 23.2 ft. scribed "T19S R9W S14 BT" continued next page

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Cor. Secs. 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>13" hemlock bears N.18$\frac{3}{4}$°E., (bearing hard to read) 29.4 ft. scribed "T19S R9W S19 BT" 17" hemlock bears N.26°W., 31.1 ft. scribed "T19S R9W S11 BT" 14" hemlock bears S.35°E., 20.0 ft. scribed "T19S R9W S13 BT"</p>
<p>Fd. BC & BTs; & steel post adjacent to corner by R. Rice 2/2014 - M167-43</p>
<p>BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2799, surveyed Aug. 2015 - (DCSO records Vol. 58 Page(s) 23422 & T19-9 2017-1 plat) ----- The cor. of secs. 11, 12, 13, & 14, perpetuated by Ward, in 2002, monumented with an iron post, 2$\frac{1}{2}$" dia., firmly set, projecting 8" above ground, with a brass cap (properly) mkd. (A magnet in a white plastic case was deposited at the base of each stainless steel post.) from which the remains of BTs mkd. by Tillman, et al, in 1957-58 A fir stump, 25" dia., bears N.9°E., 32.3 ft., with a healed blaze. A fir stump, 47" dia., bears S.57°E., 127.4 ft., with illegible scribe marks visible on an open blaze. A fir stump, 32" dia., bears S.30°W., 7.9 ft., with no marks visible. and the remains of the BTs mkd. by Ward A hemlock, 18" dia., bears N.18$\frac{3}{4}$°E., 29.6 ft., with illegible scribe marks visible on a partially healed blaze. A hemlock, 20" dia., bears S.35$\frac{1}{4}$°E., 19.9 ft. with illegible scribe marks visible on a partially healed blaze. A fir stump, 12" dia., bears S.43°W., 22.9 ft., with a healed blaze. A hemlock, 22" dia., bears N.26$\frac{1}{4}$°W., 31.0 ft., with illegible scribe marks visible on a partially healed blaze. No suitable accessories available in sec. 14. An aluminum fence post is alongside the cor. NAD 1983 (2011) Latitude: 43°55'45.86"N Longitude: 123°43'42.73"W</p>