

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 205)

Set a post 4 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face; from which

A Fir 30" dia., bears S.13½°E., 10 lks. dist., mkd. ¼ S BT

A Fir 24" dia., bears N.29°W., 29 lks. dist., mkd. ¼ S BT.

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12460)

The ¼ sec. cor. of sec. 1, determined from the original bearing trees, as follows:

A Fir 30" dia., bears S.13½°E., 10 lks. dist. mkd. ¼ S BT on bark blaze.

A Fir 24" dia., bears N.29°W., 29 lks. dist. with faint scribe marks visible on badly scaled bark blaze.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd:

¼ S 1

1953

from which new bearing trees,

A Fir 24" dia., bears S.55¼°E., 59 lks., mkd. ¼ S1 BT.

A Fir 16" dia., bears S.69°W., 42 lks. mkd. ¼ S1 BT

Wayne R. Donovan, LS #2553 - Mike Kessler - 5/19/93 - C.S. File 63/153-56

Found - 1953 G.L.O. Brass cap in good condition.

2½" brass cap bears N.89°12'50"W., 81.75' - (¼ cor. sec. 36.)

22" Fir, stump bears S.55½°E., 37.8', visible scribing.

20" Fir, stump bears S.69°W., 27.4', healed face.

New BTs- 17" Fir, bears S.22½°W., 53.8', blazed & scribed "¼ S1 BT"

10" Fir, bears S.43 ¾°E., 15.6', blazed & scribed "¼ S1 BT"

Corner lies on a gradual NW slope.

Ron Rice, NW Land Surveying - Jason Collver - May 2012 - C.S. File 65/76-51

Condition report only

Found - 2½" GLO brass cap on iron pipe, dated 1953
continued next page

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 642100

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 1 only, T20-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

22" Fir, stump bears S.55½°E., 37.8', visible scribing.(Found in same condition)
20" Fir, stump bears S.69°W., 27.4', healed face. (Found in same condition)
17" Fir, bears S.22½°W., 53.8', blazed & scribed "¼ S1 BT" (Found 21" Fir with healed face)
10" Fir, bears S.43¾°E., 15.6', blazed & scribed "¼ S1 BT" (Found 16" Fir with healed face)
Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.
Compass Declination 16° East

Fd. BC & accessories per rec. by R.Rice - Mar 2015 - M169-27

BLM Dependent Resurvey by Jason A Lightbown, Cadastral Surveyor, Under Group No. 2841, Surveyed June/Oct. 2016 - (DCSO records Vol. 59 Page(s) 23602-3)

The ¼ sec. cor. of sec. 1 only, perpetuated by Donovan, in 1993; monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd. from which the remains of an original bearing tree
A fir stump, 24" dia., bears N.29°W., 19.1 ft., no marks visible.
and the remains of the BTs mkd. by Tillman and Gawron in 1953-54
A decayed fir stump, 14" dia., bears S.55½°E., 37.6 ft., with a healed blaze.
A decayed fir stump, 13" dia., bears S.68½°W., 27.6 ft., with ¼ visible on open blaze.
and the bearing trees mkd. by Donovan
A fir, 18" dia., bears S.44¾°E., 15.4 ft., with a healed blaze.
A fir, 21" dia., bears S.23¼°W., 54.2 ft., with a double healed blaze.

2